

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23003262/RVP3E2**Date:** 28/04/2023REFERENCE

Insured/Claimant:	PREMIUM LEASING PTE LTD	Policy No:	0999993549
Date of Loss:	15/03/2023	Nature of Claim:	OD Claim No: 1251529171SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6350E		
Make & Model:	AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A)	Engine No:	DAX031529
Reg. Date:	13/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF9J2129114
Colour:	White	Odometer:	46341 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$151,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,960.00	6,759.00	4,201.00	38.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,652.00	2,552.00	3,100.00	54.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,612.00	9,311.00	7,301.00	43.95
+ GST 8.00/8.00% (S\$)	1,328.96	744.88	584.08	43.95
Nett Amount (S\$)	17,940.96	10,055.88	7,885.08	43.95

INSPECTION

Date of Assignment:	29/03/2023		
Date Inspected:	28/03/2023	Inspected At:	281 Alexandra Road Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that insured decided not to proceed the claim of own damage

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,377.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER - UPPER	Deformed	2,152.00 FS	*2,152.00 FS
2	1		*REAR BUMPER - LOWER	Deformed	1,409.00 FS	*1,409.00 FS
3	1		*REAR BUMPER SPOILER	Deformed	1,021.00 FS	*1,021.00 FS
4	1		*REAR BUMPER TOW EYE COVER - LH	Not Necessary	57.00 FS	*- FS
5	1		*REAR BUMPER TOW EYE COVER - RH	Missing	34.00 FS	*34.00 FS
6	1		*REAR BUMPER CLOSING ELEMENT - RH	* Check	114.00 FS	*- FS
7	1		*REAR BUMPER CHROME TRIM - RH	Not Necessary	281.00 FS	*- FS
8	1		*REAR BUMPER TAIL LIGHT - RH	Cracked	826.00 FS	*826.00 FS
9	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	491.00 FS	*- FS
10	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	129.00 FS	*- FS
11	1		*REAR AERIAL KEY ACCESS	Not Necessary	123.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	* Check	1,104.00 FS	*- FS
13	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	* Check	7.00 FS	*- FS
14	1		*REAR BUMPER HOLDING STRAP	* Check	201.00 FS	*- FS
15	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	200.00 FS	*- FS
16	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	543.00 FS	*- FS
17	4		*REAR PARKING AID SEAL RING	Necessary	11.00 FS	*11.00 FS
18	1		*SET REAR BUMPER WIRING	* Check	551.00 FS	*- FS
19	2		*REAR WHEEL COVER - LH / RH	Necessary	1,306.00 FS	*1,306.00 FS
20	1		*SUNDRIES	* Check	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	10,960.00	6,759.00
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, REAR END PANELLING AND REAR BOTH WHEEL ARCH TRIMS	New	3,500.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,652.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >