

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003264/UNP3Q2**Date:** 10/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00030062201		
Claimant Vehicle No :	SMS4941D	Insured Vehicle No :	GBL1846H		
Date of Loss:	27/03/2023	Nature of Claim:	TP	Claim No:	SNM23D202294/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS4941D	Engine No:	G4FGKU475152
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU011258
Reg. Date:	28/02/2020 (Man. Year: 2019)	Odometer:	104588 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	RAPID 6 mm	Rear Left Side:	RAPID 6 mm
Front Right Side:	RAPID 6 mm	Rear Right Side:	RAPID 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,801.84	3,192.24	6,609.60	67.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,990.00	2,510.00	55.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,301.84	5,182.24	9,119.60	63.77
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	14,301.84	4,100.00	10,201.84	71.33

INSPECTION

Date of Assignment:	29/03/2023		
Date Inspected:	29/03/2023	Inspected At:	130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 Repairer:Zoom Autowerks Pte Ltd (HQ)
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS4941D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	80.80 FL	*80.80 FL
2	1		*REAR TAILLAMP -RH	Not Necessary	1,089.60 FL	*- FL
3	1		*REAR BUMPER	Torn	459.40 FL	*459.40 FL
4	1		*REAR BUMPER SIDE BRACKET	Cracked	80.90 FL	*45.00 FL
5	1		*REAR BUMPER INNER SPONGE	Not Necessary	166.30 FL	*- FL
6	1		*REAR BUMPER LOWER DIFFUSER	Not Necessary	353.50 FL	*- FL
7	1		*REAR BUMPER REFLECTOR	Not Necessary	179.50 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	*- FL
9	2		*REAR BUMPER PDC SENSORS	Not Necessary	375.80 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER (O/S)	Cracked	78.00 FL	*78.00 FL
11	1		*REAR FENDER -RH	Badly Dented	2,300.60 FL	*2,109.20 FL
12	1		*REAR FENDER INNER SHIELD	Deformed	189.00 FL	*189.00 FL
13	1		*REAR DOOR -RH	Repair	1,831.20 FL	*- FL
14	1		*REAR DOOR RUBBER	Not Necessary	130.50 FL	*- FL
15	1		*REAR WHEEL HUB WITH BEARING	Damaged	366.40 FL	*366.40 FL
16	1		*REAR SHOCK ABSORBER	Not Necessary	388.20 FL	*- FL
17	1		*REAR AXLE BEAM	Not Necessary	1,900.30 FL	*- FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
20	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
21	1		*REAR TYRE	Serviceable	400.00 FS	*- FS
22	1		*REAR WHEEL RIM -RH	Warped	1,000.00 FS	*450.00 FS
					Sub Total (\$\$)	11,854.80 3,857.80
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,052.96 665.56
					Total Parts (\$\$)	9,801.84 3,192.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	40.00
4	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	120.00
5	TO CONDUCT WHEEL ALIGNMENT	New	180.00	80.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS TRANSFER ALL FITTINGS TO NEW DOOR	New	180.00	0.00
8	TO APPLY UNDERCOATING	New	150.00	30.00
9	PANEL BEATING	New	1,600.00	800.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	700.00
Gross Labour Cost (S\$)			4,500.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >