

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003269/KQP3M4**Date:** 31/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00067742200		
Claimant Vehicle No :	GBA3636S	Insured Vehicle No :	YN2107T		
Date of Loss:	14/03/2023	Nature of Claim:	TP	Claim No:	SNM23D201942/C02/TANKL/LK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA3636S	Engine No:	10Q4DR0027743
Make & Model:	PEUGEOT PARTNER, 1.5 BLUEHDI EAT8 LWB (A)	Chassis No:	VR3EFYHZRLJ958907
Reg. Date:	27/08/2021 (Man. Year: 2020)	Odometer:	40080 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 9 mm	Rear Left Side:	Falken 9 mm
Front Right Side:	Falken 9 mm	Rear Right Side:	Falken 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,064.50	3,602.50	462.00	11.37
Miscellaneous Items	640.00	280.00	360.00	56.25
Labour	1,650.00	1,130.00	520.00	31.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,354.50	5,012.50	1,342.00	21.12
+ GST 8.00/8.00% (S\$)	508.36	401.00	107.36	21.12
Nett Amount (S\$)	6,862.86	5,413.50	1,449.36	21.12

INSPECTION

Date of Assignment:	29/03/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	11/07/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Jul 2023)	
Parts:	N/A	PEUGEOT PARTNER 1.5 BLUEHDI EAT8 LWB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA3636S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER (WCP)	Dented/Cut	550.00 F	*550.00 F
2	1		*1 PC REAR BUMPER REINFORCEMENT (WCP)	Repair	420.00 F	*- F
3	1		*1 PC LH TAILGATE (WCP)	Bent	1,200.00 F	*1,200.00 F
4	1		*1 PC LH TAILGATE EMBLEM (PARTNER) (WCP)	Necessary	45.00 F	*45.00 F
5	1		*1 PC LH TAILGATE TRIM RUBBER (WCP)	Cut	150.00 F	*150.00 F
6	1		*1 PC RH TAILGATE (WCP)	Bent	1,200.00 F	*1,200.00 F
7	1		*1 PC RH TAILGATE EMBLEM (PEUGEOT) (WCP)	Necessary	70.00 F	*70.00 F
8	1		*1 PC RH TAILGATE LOGO (WCP)	Necessary	60.00 F	*60.00 F
F=Franchise part.						
Sub Total (\$\$)					3,695.00	3,275.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					369.50	327.50
Total Parts (\$\$)					4,064.50	3,602.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC REVERSE CAMERA Serviceable	280.00	0.00
2	1	1 PC STICKER - 6 PAX Necessary	10.00	10.00
3	1	1 PC STICKER - 70KM/H Necessary	10.00	10.00
4	1	1 SET REVERSE SENSOR Scratched	200.00	200.00
5	1	1 SET TAILGATE BODY PROTECTOR Not Necessary	80.00	0.00
6	1	2 PCS TAILGATE GLASS GUM Necessary	60.00	60.00
Sub Total (\$\$)			640.00	280.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BOTH WINDSCREEN GLASS	New	140.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATES, TO KNOCK & REPAIR REAR END PANEL AND REALIGN THE SAME	New	700.00	500.00
3	PUTTY & RESPRAY ON REAR END PANEL, TAILGATES AND REAR AFFECTED AREAS	New	700.00	400.00
4	REMOVE & REFIX REAR REVERSE SENSOR, REVERSE CAMERA, INCAR CAMERA AND RESET SYSTEM	New	50.00	50.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,650.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >