

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23003273/RVY3M4**Date:** 15/05/2023**REFERENCE**

Insured/Claimant:	SOR JIN JIANG	Policy No:	MPC23P00023800	
Date of Loss:	24/03/2023	Nature of Claim:	OD	Claim No: DMPC2300210H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3418J		
Make & Model:	MAZDA 6, 2.5 4-DOOR SEDAN 2.5L SP.6EAT SR LED (A)	Engine No:	PY20849916
Reg. Date:	13/01/2017 (Man. Year: 2016)	Chassis No:	JM6GL1031H0106059
Colour:	Grey	Odometer:	80196 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R19	Rear Tyre Size:	225/45R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,580.70	1,342.00	238.70	15.10
Miscellaneous Items	60.00	30.00	30.00	50.00
Labour	1,160.00	560.00	600.00	51.72
Paintwork Labour	1,000.00	600.00	400.00	40.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,800.70	2,532.00	1,268.70	33.38
+ GST 8.00/8.00% (S\$)	304.06	202.56	101.50	33.38
Nett Amount (S\$)	4,104.76	2,734.56	1,370.20	33.38

INSPECTION

Date of Assignment:	29/03/2023	Present Location:	Accord Auto Services Pte Ltd (HQ) ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723
Date Inspected:	31/03/2023	Inspected At:	
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	MAZDA 6 2.5 4-DOOR SEDAN 2.5L SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3418J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER (WCP)	Bent	520.00 F	*260.00 F
2	1		*FRONT LH FENDER SHIELD (WCP)	Missing	65.00 F	*65.00 F
3	1		*FRONT LH FOGLAMP (WCP)	Cracked	250.00 F	*285.00 F
4	1		*FRONT LH FOGLAMP GARNISH (WCP)	Cracked	12.00 F	*20.00 F
5	1		*FRONT LH FOGLAMP CHROME (WCP)	Cracked	80.00 F	*80.00 F
6	1		*FRONT BUMPER (WCP)	Torn	500.00 F	*500.00 F
7	1		*FRONT BUMPER LH SIDE RETAINER (WCP)	Necessary	10.00 F	*10.00 F
						F=Franchise part.
					Sub Total (\$\$)	1,437.00 1,220.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	143.70 122.00
					Total Parts (\$\$)	1,580.70 1,342.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NECESSARY CLIPS (NECESSARY)	60.00	30.00
Sub Total (\$\$)			60.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Spray Painting to All Affected Areas	New	1,000.00	600.00
Labour Items				
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area (*Front LH Door & LH Rocker Panel)	New	1,000.00	500.00
3	Check Wiring System & Light	New	80.00	0.00
4	To Check & Adjust Front Wheel Aligment	New	80.00	60.00
Gross Labour Cost (\$\$)			2,160.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >