

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23P00023800	Date of Loss:	24/03/2023
Vehicle Reg. No.:	SLK3418J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SOR JIN JIANG		
Make/Model:	MAZDA 6, 2.5 SEDAN SP.6EAT SR LED (A)	Vehicle Reg. Date:	13/01/2017
Vehicle Colour:	GREY		
Engine No:	PY20849916	Chassis No:	JM6GL1031H0106059
Odometer:	79964 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Remarks:	REQUEST PROCESS PART BY PARTS REPAIR.NO USED PARTS AVAILABLE. AT BUKIT MERAH CONTACT PERSON 92740999.		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,580.70
Miscellaneous Items	60.00
Labour	1,160.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (\$\$)	3,800.70
+ GST 8.00% (\$\$)	304.06
Nett Amount (\$\$)	4,104.76

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2023)

Parts: 143 MAZDA 6 2.5 SEDAN SP.6EAT SR LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT LH FENDER <i>lt</i> ✓	0.00	0.00	*520.00 F
2	1		*FRONT LH FENDER SHIELD <i>MIS</i> ✓	0.00	0.00	*65.00 F
3	1		*FRONT LH FOGLAMP ?	0.00	0.00	*250.00 F
4	1		*FRONT LH FOGLAMP GARNISH <i>crn</i> ✓	0.00	0.00	*12.00 F
5	1		*FRONT LH FOGLAMP CHROME <i>crn</i> ✓	0.00	0.00	*80.00 F
6	1		*FRONT BUMPER <i>tan</i> ✓	0.00	0.00	*500.00 F
7	1		*FRONT BUMPER LH SIDE RETAINER <i>lv</i> ✓	0.00	0.00	*10.00 F

F=Franchise part.

Sub Total (\$\$)	1,437.00
+ Margin on L,N Items 10.00% (\$\$)	143.70
Total Parts (\$\$)	1,580.70

Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	NECESSARY CLIPS	30	60.00
Sub Total (S\$)				60.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	Spray Painting to All Affected Areas	New	600	1,000.00
---	--------------------------------------	-----	-----	---------------------

Labour Items

2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area (*Front LH Door & LH Rocker Panel)	New	500	1,000.00
3	Check Wiring System & Light	New	X	80.00
4	To Check & Adjust Front Wheel Alignment	New	60	80.00

Gross Labour Cost (S\$) 2,160.00

Accord Auto Services Pte Ltd/SLK3418J/29/03/2023 09:34. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
5 days
1/3 P/P
31/03/23 @ 1500
EXESS: TBA
Revert
Rating after repair