



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF23003275/Kny3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1			Date:	12/04/2023
HEMMANT ROADSINGAPORE 438675				
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 1204U	Veh. Inspected	GBF 3192D	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2023/018	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	29/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFAT35Y20K206816	Colour	SILVER	
Odometer	155475 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	YOKOHAMA	9 mm	
L/H Front Tyre	195 R15X8	YOKOHAMA	9 mm	
R/H Rear Tyre	155 R12X8 (D)	ARIVO	9/9 mm	
L/H Rear Tyre	155 R12X8 (D)	ARIVO	9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2023	Inspection Date	31/03/2023	
Survey held at	RS AUTO SERVICES 160 SIN MING DRIVE SIN MING AUTOCITY # 06-01 SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	