

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG23003277/RQY3E2**Date:** 03/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700075224
Claimant Vehicle No :	FBT2417P	Insured Vehicle No :	SLN9633Z
Date of Loss:	25/03/2023	Nature of Claim:	TP
		Claim No:	6325966682SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBT2417P	Engine No:	G3L8E0769235
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG5680MK103714
Reg. Date:	17/12/2021 (Man. Year: 2021)	Odometer:	16417 km
Colour:	Red		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	IRC 4 mm	Rear Left Side:	IRC 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/03/2023	
Date Inspected:	29/03/2023	Inspected At: Speedway Motor Pte Ltd (Toh Guan) No. 36 Toh Guan Road East #01-32 Enterprise Hub Singapore 608580
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$15,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
2	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	1		*FRONT HEADLAP	Scratched	0.00 F	*- F
4	1		*FRONT WINDSHIELD	Missing	0.00 F	*- F
5	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
6	1		*HANDLE BAR	Bent	0.00 F	*- F
7	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
8	1		*HANDLE BAR BALANCER LH	Scratched	0.00 F	*- F
9	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
10	1		*SIDE FAIRING LOWER GARNISH	Scratched	0.00 F	*- F
11	1		*CENTER FAIRING	Scratched	0.00 F	*- F
12	1		*REAR FAIRING LH	Scratched	0.00 F	*- F
13	1		*FRONT FAIRING GARNISH	Deformed	0.00 F	*- F
14	1		*FRONT AIR-GRILLE	Deformed	0.00 F	*- F
15	1		*SIDE FAIRING LH	Scratched	0.00 F	*- F
16	1		*LH SIDE FAIRING LOWER GARNISH	Scratched	0.00 F	*- F
17	1		*REAR BOX	Scratched	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >