

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: HSBC SHC 3185U
 Policy No. VFX/P2419138
 Claims No. S3M04JU8
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 07 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT

Veh No: SNG 9069 R Yr Regr: 02103/2017
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Honda HRV 15 DX cc 1496Colour: Silver A/C: Insured / Std / HI / NASp. Reading: 78254 T/Radio: Insured / Std / HI / NAEng/No: L15B4532391C/No: JHPRU1310GX2023*90

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or _____

Brake: In Order / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD / Rim or _____

Tyre Size: F: 215/60 R16R: 215/60 R16

BS / DUB / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A. 2410312023 D.O.I. 0110312023 1307 31/3/23Survey held at TY Autocare Services

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
	Repair Range	Balance: 53.3M
	07 days	Yearly: \$13k
	\$7k - \$8k	ARF 50%: \$7304
7/3/23	Submit PRS, repair range \$7,000-\$8,000	MV: \$63k
		LTA: 29,731
28/4/23	Submit LS \$7650 (red 6600, 46%)	NV: \$33,269
		Dismantle: 0210312023

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: X 6

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 7/3/23-typist

28/4/23-typist

Report Format: TP RES

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inva (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ = RS. \$

Photos

Others

TOTAL

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Anna Peh Pei Yan
Blk 613 Woodlands Ave 4
#12-479
Singapore 730613

Date : 10/03/2023

Reference No : CAS/23-03/015

General Information

Registration No. : SNG 9069R
Accident Date : 24/02/2023

Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Honda HRV
Engine Capacity	: 1496 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 078254	Engine No.	: L15B4532391
Chassis No.	: JHMRU1810GX202390	Steering	: In Order
Registration Date	: 02/08/2017	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	70%
L/H Front Tyre	215/60R16	DUNLOP	70%
R/H Rear Tyre	215/60R16	DUNLOP	70%
L/H Rear Tyre	215/60R16	DUNLOP	70%

Inspection

Repairer : TY Autocare Services
Blk 5033 Ang Mo Kio Industrial Park 2 #01-271 Singapore 569536

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$20,910.40
Revised Amount : \$14,250.00
Less Excess : -
Nett Total : \$14,250.00

Remarks

- (A) Survey was done on 27/02/2023
- (B) Re-survey was done on 01/03/2023
- (C) Re-survey after repair was done on 06/03/2023
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – LIST ITEMS</u>				
1	1pc	Tailgate <i>Replace</i>	Dented/Buckled	1,287.60	1,287.60	953
2	1set	Tailgate glass moulding <i>Replace</i>	Necessary	121.60	121.60	✓
3	1pc	Tailgate outer garnish <i>Replace</i>	Broken	481.90	481.90	X NN
4	1pc	Tailgate emblem 'H' <i>Replace</i>	Necessary	58.80	58.80	X NN
5	1pc	Tailgate emblem 'HRV' <i>Replace</i>	Necessary	86.90	86.90	32
6	1pc	Tailgate emblem 'I-Vtec' <i>Replace</i>	Necessary	89.90	89.90	35
7	2pcs	Tailgate lamp @ \$510.60 <i>Replace</i>	Cracked/Broken	1,021.20	1,021.20	922
8	2pcs	Tailgate licence lamp @ \$42.00	Serviceable	84.40	-	X
9	1pc	Tailgate outer pull switch	Serviceable	191.60	-	X
10	1pc	Tailgate inner trim board <i>Replace</i>	Deformed/Broken	582.60	582.60	392.4
11	1pc	Tailgate inner lock <i>Replace</i>	Bent/Jammed	310.60	310.60	189.4
12	1pc	Tailgate inner pull pocket <i>Replace</i>	Deformed	86.90	86.90	40
13	1pc	Tailgate weatherstrip <i>Replace</i>	Distorted	211.40	211.40	79.20
14	2pcs	Tailgate hinge @ \$65.50 <i>Repair</i>	Repair	131.00	-	X
15	2pcs	Tailgate damper @ \$181.60	Serviceable	363.20	-	X
16	2pcs	Tailgate stopper @ \$18.20 <i>Replace</i>	Necessary	36.40	36.40	X NN
17	2pcs	Taillamp @ \$560.90 <i>Replace</i>	Cracked/Broken	1,121.80	1,121.80	978.4
18	2pcs	Taillamp filler panel @ \$261.90	Repair	523.80	-	X
19	1pc	Rear bumper <i>Replace</i>	Dented/Broken	829.60	829.60	492
20	2pcs	Rear bumper reflector @ \$68.60 <i>Replace</i>	Cracked/Broken	137.20	137.20	106.24
21	2pcs	Rear bumper side @ \$241.20 <i>Replace</i>	Dented/Torn	482.40	482.40	390
22	2pcs	Rear bumper side retainer @ \$48.90 <i>Replace</i>	Necessary/Broken	97.80	97.80	64
23	1pc	Rear end panel <i>Replace</i>	Dented/Buckled	759.10	759.10	397
24	1pc	Rear end panel garnish <i>Replace</i>	Deformed	265.20	265.20	215.3
25	1pc	Rear exhaust silencer <i>Repair</i>	Dented/Bent	547.60	547.60	✓ X
26	1pc	Rear exhaust silencer heat shield <i>Replace</i>	Dented/Warped	99.60	99.60	60
27	1pc	Rear floor board <i>Replace</i>	Dented/Torn	495.90	495.90	250
28	1pc	Rear floor tool tray <i>used back</i>	Deformed/Broken	361.90	361.90	✓ CRA X
29	1pc	Rear floor panel <i>Replace</i>	Dented/Buckled	965.80	965.80	✓
30	1pc	Rear floor panel side member LH <i>Repair</i>	Bent/Twisted	391.80	391.80	✓ X
31	1pc	Rear floor panel undercover <i>Replace</i>	Deformed/Broken	281.60	281.60	✓
32	2pcs	Rear fender arch garnish @ \$261.90 <i>Replace</i>	Torn/Broken	523.80	523.80	397.6
33	2pcs	Rear fender inner trim board @ \$581.90 <i>Replace</i>	Deformed/Broken	1,163.80	1,163.80	950

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)	
		<u>PARTS REPLACEMENT – LIST ITEMS (CONT'D)</u>				
34	1pc	Rear smart keyless antenna <i>Replace</i>	Damaged	195.60	195.60	✓
35	1pc	Rear smart keyless buzzle <i>Replace</i>	Broken	199.50	199.50	✓
36	1pc	Rear side chassis member LH <i>Repair</i>	Bent/Twisted	670.60	670.60	
		Sub total		15,260.40	13,966.40	
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>				
1	1set	Tailgate glass sealant	Necessary	100.00	80.00	60 50
2	1set	Tailgate glass foam tape	Necessary	65.00	45.00	40 20
3	1set	Tailgate top spoiler clip	Necessary	80.00	50.00	30
4	1set	Tailgate outer garnish clip	Necessary	80.00	50.00	30
5	1set	Rear bumper clip	Necessary	45.00	30.00	✓
6	1set	Reverse sensor	Damaged	280.00	220.00	200
7	1pc	Reverse camera	Serviceable	550.00	-	x
		Part total		16,460.40	14,441.40	
		<u>LABOUR & MISC. CHARGES</u>				
1		To remove, refix tailgate glass		150.00	120.00	✓
2		To transfer tailgate mechanism		150.00	80.00	60
3		To remove & refix rear exhaust silencer		100.00	70.00	✓
4		To check rear electrical wiring		50.00	20.00	✓
5		To remove, refix rear trim & garnish		100.00	80.00	60
6		To remove, refix rear seat & carpet		130.00	100.00	x
7		To remove, refix reverse sensor & camera		120.00	80.00	50
8		To respray undercoating		150.00	100.00	60
9		To respray painting & etc		1,500.00	1,200.00	800
10		Panel beating, remove & replacing above parts		2,000.00	1,500.00	1000
		Grand total		20,910.40	17,791.40	
Recommended cost of lump sum repair (To its pre-accident condition)					14,250.00	

06 days

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$14,250.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

Constant Appraiser Services



Lin Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA