



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 8988J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,603.00	1,603.00
2	REAR BUMPER SIDE HOLDER @\$145.00	NOT NECESSARY	290.00	-
2	REAR BUMPER REFLECTOR @\$75.00	NOT NECESSARY	150.00	-
1	REAR BUMPER UNDERCOVER	CRACKED	198.00	198.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	729.00	-
1	REAR BUMPER REINFORCEMENT COVER	CRACKED	179.00	179.00
1	REAR BUMPER CENTRE GUIDE	CRACKED	205.00	205.00
4	REVERSE SENSOR @\$260.00	DAMAGED (1PIECE ONLY)	1,040.00	260.00
4	REVERSE SENSOR HOLDER @\$25.00	NECESSARY	100.00	100.00
2	TAILLAMP @\$692.00	NOT NECESSARY	1,384.00	-
	LESS 5% DISCOUNT		-293.90	-
	LESS 10% DISCOUNT		-	-254.50
			5,584.10	2,290.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER UNDERCOVER CLIPS (SN)	NECESSARY	20.00	20.00
			70.00	70.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS.		500.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		500.00	200.00
	WIRING CHECK.		50.00	30.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,300.00	480.00
	GRAND TOTAL		6,954.10	2,840.50



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,250.00
---	--	--	----------

Report Ref No. CS/SMR23003282/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.