



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 9561E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	612.00	-
2	REAR BUMPER SIDE BRACKET L/R	NOT NECESSARY	70.00	-
1	REAR BUMPER CENTER BEAM	NOT NECESSARY	154.00	-
1	REAR BUMPER LOWER LIP	TO REPAIR SEE LABOUR	653.00	-
1	REAR RH TAILLAMP	NOT NECESSARY	315.00	-
1	REAR RH TAILLAMP CLIPS	NOT NECESSARY	11.00	-
	LESS 10% DISCOUNT		-181.50	-
			1,633.50	-
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			340.00	-
<u>LABOUR</u>				
	REFIT AND REALIGN REAR BUMPER AND LOWER SPOILER. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER LIP.		150.00	150.00
	SPRAY PAINTING.		400.00	300.00
	CHECK LIGHTING, REVERSE SENSOR WIRING.		60.00	30.00
	SPRAY TUFF COAT.	NOT NECESSARY	100.00	-
			710.00	480.00
GRAND TOTAL			2,683.50	480.00
RECOMMENDED COST OF REPAIRS				480.00

Report Ref No. CS/FCI23003287/Wny3e2

MARKET VALUE: \$68,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$15,828.00=NETT VALUE: \$52,172.00

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.