

ASS. REC. BY:

REF:

AGZ/23003289/KV

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SFN 8381C

Policy No.

Claims No.

C10021364/JL

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$63K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SBQ 6888C

Yr Regn:

03, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

C.C.

1597

Colour

M-Black

A/C:

Insured / Std / NI / NA

Sp.Reading

101626

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NRHFC 56506 T001251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/3/23

D.O.I.

4/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA & EM not ready

13/4 L/Ry @ 3300 Cnkr (red 7525.60, 69%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/4/23-typist

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / L.B.: (\$ 3300)

Repair Estimate


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: 82636295 Email: thiamhenghuat@gmail.com

Not Authorized
1/Sup @ 3300h
Resony After Rain
3 days

Make/Model: HONDA CIVIC 1.6
Engine/Chassis No.: MRHFC5650GT001251
Date of accident: 24.03.23
Damaged area: Front

Date: 04/04/2023
Claim Type: TP
VRN: SBQ6888C



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	SUPPORT PANEL TOP GARNISH	1	\$ 384.00	\$ 384.00
2	FRONT BUMPER LOWER BEAM 312.60	1	\$ 368.00	\$ 368.00
3	FRONT BUMPER - LOWER 549.90	1	\$ 1,041.00	\$ 1,041.00
4	FRONT BUMPER - TOP PANEL	1	\$ 367.00	\$ 367.00
5	FRONT BUMPER SIDE RETAINER 112.0 42.60	2	\$ 555.00	\$ 1,110.00
6	FRONT BUMPER LOWER GRILLE	1	\$ 356.00	\$ 356.00
7	HEADLAMP ASSY TOP CHROME C95.80	2	\$ 253.00	\$ 506.00
8	HEADLAMP ASSY C1030	2	\$ 1,805.00	\$ 3,610.00
9	HEADLAMP LOWER BRACKET	2	\$ 52.00	\$ 104.00
10	FRONT GRILLE TOP BRACKET	1	\$ 39.00	\$ 39.00
11	FRONT GRILLE TOP GARNISH	1	\$ 87.00	\$ 87.00
12	FRONT GRILLE LOGO 38	1	\$ 98.00	\$ 98.00
13	FRONT GRILLE INNER 214.50	1	\$ 436.00	\$ 436.00
14	FRONT GRILLE OUTER - CHROME 160	1	\$ 324.00	\$ 324.00
15	FRONT GRILLE TOP BRACKET	2	\$ 29.00	\$ 58.00
16	A/C CONDENSER 704.40	1	\$ 1,249.00	\$ 1,249.00
Subtotal				\$ 10,137.00
List discount				20.00%
Total				\$ 8,109.60

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	HEADLAMP TOP RUBBER STRIP	2	\$ 24.00	\$ 48.00
2	SUPPORT PANEL TOP GARNISH CLIP	8	\$ 3.50	\$ 28.00
3	FRONT BUMPER CLIP	10	\$ 3.50	\$ 35.00
4	FRONT NUMBER PLATE WITH FRAME	1	\$ 55.00	\$ 55.00
5	SUNDRIES	1	\$ 50.00	\$ 50.00
Total				\$ 216.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
5	To remove and refit a/c condenser for replacement. To recharge system & check a/c functionality.	0.75	\$ 150.00
Total labour			\$ 2,500.00
Estimate Grand Total			\$ 10,825.60

300

200

300

X

100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: