



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Tng Kiah Yong
c/o Infinity Capital & Insurance
39, Woodlands Close
#01-08, MEGA@Woodlands
Singapore 737856

Report No : RW/0014/23TP
Date : 17.03.2023

VEHICLE INSPECTION REPORT

REFERENCE

Requested by : Workshop, owner's behalf
Date of Request : 06.03.2023
Date of Accident : 03.03.2023
Date of Inspection : 06.03.2023
Inspected at : Infinity Capital & Insurance
39, Woodlands Close, MEGA@Woodlands
#01-08, Singapore 737856

VEHICLE DETAILS

Vehicle No.	: SCP 32 M	Make & Model	: Lexus ES250
Year Make	: 2016	Colour	: Grey
Engine No.	: 2ARF166008	Chassis No.	: JTHBJ1GG702090801
Engine Capacity	: 2494 cc	Mileage	: 139,612 km
Air-Con	: Yes	Radio/CD/Cassette	: Yes
Seat Belt	: Yes	Rims	: Sport

GENERAL CONDITION OF VEHICLE

General Condition	: Good	Modification	: Nil
Brakes	: Serviceable	Handbrake	: Serviceable
Steering	: Serviceable		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	Bridgestone	255/35 ZR19	Sport	6 mm
Front Left	Bridgestone	255/35 ZR19	Sport	6 mm
Rear Right	Bridgestone	255/35 ZR19	Sport	6 mm
Rear Left	Bridgestone	255/35 ZR19	Sport	6 mm

ASSESSMENT

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 15,630.23	\$ 15,506.21
Labour Charges	: \$ 1,810.00	\$ 1,410.00
Paint Work	: \$ 1,100.00	\$ 900.00
Towing Charges	: \$ -	\$ -
Total	: <u>\$ 18,540.23</u>	<u>\$ 17,816.21</u>
Recommend lump sum repairs	: \$ 14,250.00	
Reduction	: \$ 4,290.23	
Estimated Period Required for Repair	: <u>6 days</u>	



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Page : 1

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SCP 32 M

Report No.: RW/0014/23TP

<u>S/No</u>	<u>QTY</u>	<u>Description</u>	<u>Condition/ Remarks</u>	<u>Repairer's Estimates</u>	<u>My Recommendation</u>
<u>REPLACEMENT OF DAMAGED PARTS</u>					
1)	1	Front bumper	Cracked	\$ 1,016.60 N	\$ 1,016.60 ✓
2)	1	Front bumper side holder RH	Necessary	\$ 89.60 N	\$ 89.60 ✓
3)	1	Front bumper fog lamp RH	Cracked	\$ 330.90 N	\$ 330.90 ✓
4)	1	Front bumper fog lamp cover RH	Distorted	\$ 62.40 N	\$ 62.40 ✓
5)	1	Front bumper fog lamp chrome moulding RH	Cracked	\$ 78.40 N	\$ 78.40 ✓
6)	1	Front bumper reinforcement	Bent	\$ 498.80 N	\$ 498.80 Xnn
7)	1	Front bumper sponge	Serviceable	\$ 137.80 N	\$ - Xnn
8)	1	Front bumper sensors RH	Failed	\$ 269.40 N	\$ 200 269.40 ✓
9)	1	Front fender RH	Dented	\$ 1,339.60 N	\$ 1,339.60 ✓
10)	1	Front fender inner shield RH	Distorted	\$ 295.20 N	\$ 295.20 ✓
11)	1	Front wheel rim RH	Dented	\$ 1,918.70 N	\$ 1,918.70 700 ✓
12)	1	Front lower arm RH X	Bent	\$ 549.80 N	\$ 549.80 Xnn
13)	1	Front shock absorber RH X	Bent	\$ 743.70 N	\$ 743.70 Xnn
14)	1	Front knuckle arm RH X	Distorted	\$ 959.70 N	\$ 959.70 Xnn
15)	1	Front wheel hub c/w bearing	Distorted	\$ 594.10 N	\$ 594.10 ✓
16)	1	Front anti roll bar linkage RH X	Bent	\$ 95.60 N	\$ 95.60 Xnn
17)	1	Front drive shaft RH X	Distorted	\$ 1,562.70 N	\$ 1,562.70 Xnn
18)	1	Wiper washer tank	Dented	\$ 137.60 N	\$ 137.60 ✓
19)	1	Front headlamp RH	Broken	\$ 6,185.20 N	\$ 6,185.20 ✓
20)	1	Front headlamp lower bracket RH	Cracked	\$ 78.90 N	\$ 78.90 ✓
				\$ 16,944.70	\$ 16,806.90
Less 10%				\$ 1,694.47	\$ 1,680.69
				\$ 15,250.23	\$ 15,126.21
21)	1set	Front bumper clips	Necessary	\$ 50.00 SN	\$ 30 50.00 ✓
22)	1set	Front fender inner shield clips	Necessary	\$ 30.00 SN	\$ 30.00 ✓
23)	1	Front tyre RH	Cut	\$ 300.00 SN	\$ 300.00 Xnn
Total (Parts):				\$ 15,630.23	\$ 15,506.21

LABOUR CHARGES

24)	Panel beat front bonnet and front support panel. Straighten front right chassis. Remove and replace all damaged parts.	\$ 1,000.00	\$ 800.00 500
25)	Computerise wheel alignment.	\$ 150.00	\$ 120.00 80
		<u>\$ 16,780.23</u>	<u>\$ 16,426.21</u>



RW AUTOMOTIVE APPRAISERS SERVICES
(Licensed Appraisers Claims Adjusters)
256 Bishan St. 22 #12-472 Singapore 570256
Tel +65 6996 9988 Hp: +65 8338 9988
Email: rw9988@yahoo.com Reg. 52821270B

Page : 2

Vehicle No: SCP 32 M

Report No.: RW/0014/23TP

Balance brought forward	\$ 16,780.23	\$ 16,426.21
26) Remove and reinstall front right undercarriage.	\$ 400.00	\$ 320.00 ¹⁵⁰
27) Check lightings and wiring.	\$ 100.00	\$ 30 50.00 ³⁰
28) Rust proofing treatment on affected area.	\$ 160.00	\$ 120 0.00 ³⁰
29) Spray painting on affected area.	\$ 1,100.00	\$ 900 0.00 ⁵⁰⁰
Total (Labour):	\$ 2,910.00	\$ 2,310.00
Total:	<u>\$ 18,540.23</u>	<u>\$ 17,816.21</u>

POINT OF IMPACT

At the right side front of the vehicle.

RECOMMENDATION

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$17,816.21.

CONCLUSION

The repairer has agreed to undertake repairs at a lump sum of \$14,250.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE

RICHARD WONG
(Licensed Appraiser)