Qualified Automobile Accident Damage Appraisers/Loss Adjusters 601, Choa Chu Kand Street 62, # 04-07, Singapore 680601

E-mail address: aasschee@gmail.com Mobile Number: 96623655 RCB No. 43037800M

### VEHICLE INSPECTION REPORT

To:		Ong Thye @ Ong Thai c/o Kuo Li Auto Workshop Block 5035, # 01-363 Ang Mo Kio Industrial Par		Report No	:	TP/0004/02/2023	•	
		Singapore 569538	K 2	Date	٤.	23 February 2023		
REFERENCE								
Requested by	1	Ong Thye @ Ong Thai		3rd Party Vehicle No.		YP 8258R		
Date of Request	:	14 February 2023		Owner's Vehicle No.	•	GBB 6973T		
Date of Accident	:	11 February 2023		Sum Insured	:	Not Available		
Date Inspected	:	14 February 2023		Policy No.	:	Not Available		
Inspected at	:	Kuo Li Auto Workshop		Claim No.	:	Not Available		
PARTICULARS OF	VEHI		Vahiala Madal II	ED70DD15DDEA		Air Conditioner		Vec
Reg. No.	: :	GBB 6973T	Vehicle Model	FB70BB15RDEA		Air Conditioner		Yes
Reg. No. Vehicle Make	VEHI : :	GBB 6973T Mitsubishi	Engine No. :	4M42A74640		Radio/Cassette	:	Yes
Reg. No. Vehicle Make Original Regn Date	: : :	GBB 6973T Mitsubishi 05 November 2009	Engine No. : Chassis No. :	4M42A74640 FB70BBA20120		Radio/Cassette Seat Belt	:	Yes Yes
Reg. No. Vehicle Make Original Regn Date Lifespan Expiry Date	: : :	GBB 6973T Mitsubishi 05 November 2009 04 November 2029	Engine No. : Chassis No. : Propellant :	4M42A74640 FB70BBA20120 Diesel		Radio/Cassette Seat Belt Colour	:	Yes Yes White
Reg. No. Vehicle Make Original Regn Date Lifespan Expiry Date	: : :	GBB 6973T Mitsubishi 05 November 2009	Engine No. : Chassis No. :	4M42A74640 FB70BBA20120		Radio/Cassette Seat Belt	:	Yes Yes White
Reg. No. Vehicle Make Original Regn Date	: : : : : : : : : : : : : : : : : : : :	GBB 6973T Mitsubishi 05 November 2009 04 November 2029	Engine No. : Chassis No. : Propellant :	4M42A74640 FB70BBA20120 Diesel		Radio/Cassette Seat Belt Colour	: : :	Yes Yes
Reg. No. Vehicle Make Original Regn Date Lifespan Expiry Date COE Expiry Date	: : : : : : : : : : : : : : : : : : : :	GBB 6973T Mitsubishi 05 November 2009 04 November 2029 30 September 2024	Engine No. : Chassis No. : Propellant : Engine Capacity :	4M42A74640 FB70BBA20120 Diesel 2,977 cc.	****	Radio/Cassette Seat Belt Colour Speedometer	: : :	Yes Yes White
Reg. No. Vehicle Make Original Regn Date Lifespan Expiry Date COE Expiry Date	: : : : : : : : : : : : : : : : : : : :	GBB 6973T Mitsubishi 05 November 2009 04 November 2029 30 September 2024	Engine No. : Chassis No. : Propellant : Engine Capacity :	4M42A74640 FB70BBA20120 Diesel 2,977 cc.		Radio/Cassette Seat Belt Colour Speedometer	: : :	Yes Yes White
Reg. No. Vehicle Make Original Regn Date Lifespan Expiry Date COE Expiry Date  CONDITION OF TORIGHT Front	: : : : : : : : : : : : : : : : : : : :	GBB 6973T Mitsubishi 05 November 2009 04 November 2029 30 September 2024 MAKE Ohtsu	Engine No. : Chassis No. : Propellant : Engine Capacity :  SIZE 195 R15	4M42A74640 FB70BBA20120 Diesel 2,977 cc.		Radio/Cassette Seat Belt Colour Speedometer  % REMAINING 50%	: : :	Yes Yes White

### DESCRIPTION OF DAMAGES

NOTE: The above vehicle was SURVEYED WITHOUT PREJUDICE

The owner's vehicle sustained damages on the rear portions.

Estimated period of repairs: 9 (Nine) working days

Repairer completed the repair in: 09 (Nine) days inclusive of Sunday and Public Holiday

Number of photographs taken at time of inspection and attached:

28 (Twenty-Eight) + 17 (Seventeen) Follow-up Survey

(After Dismantling And Damaged Spare Parts) and 08 (Eight) Follow-up Survey (After Repair/Painting) only.

SUMMARY OF REPAIR COST	<u>s</u>	
Repairer's Estimate	\$	7,729.95
Revised Parts	\$	2,113.74
Revised Labour	\$	2,260.00
Total Revised Amount	\$	4,373.74
Adjusted Amount	Lump Sum \$	3,500.00
Less: Owner's Excess	\$	N.A
Total	\$	3,500.00
Nett Total without GST	\$	3,500.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP 96623655) ENG TECH, CAE MIMI / AM SAE-A MSAAA-Accident Damage Appraiser

Qualified Automobile Accident Damage Appraisers/Loss Adjusters 601, Choa Chu Kang Street 62, # 04-07, Singapore 680601 E-mail Address: aasschee@gmail.com

Mobile Number: 96623655 RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No:

GBB 6973T

Attachment to report no. TP/0004/02/2023

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS		
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price	
REPLACEMENT OF DAMAGED PARTS	2 286 22	LUMP SUM REPAIR Dented/Bent - Allowable	LESS 25% 2,286.32	DT .
1 pc rear cargo bed tailgate cover	2,286.32 534.60	Serviceable - Not Allowed	To reuse	X
2. 2 pcs rear taillaumps @ 267.30	248.66	Bent - Not Allowed	To repair	×
2 pcs rear taillamp panels @ 124.33     2 pcs rear number plate lamps @ 139.00	278.00	Serviceable - Not Allowed	To reuse	x X
<ol> <li>2 pcs rear number plate lamps @ 139.00</li> <li>1 pc rear end panel</li> </ol>	845.37	Affected (Dented) - Not Allowed	To repair	×
6. I pc air duct	512.00	Cracked - Allowable	512.00	CRO
o. I pe an duci	312.00	Classes - Allowable		CICC
	4,704.95		2,798.32	
			699.58	
			200000000	
			2,098.74	/
7. 1 pc rear number plate S,Nett	50,00	Serviceable - Not Allowed	To reuse	x
8. 1 pc rear cargo bed tailgate '70 Km/h' sticker S.Nett	15.00	Necessary/Damage if removed - Allowable	15.00	~
	*******			
	4,769.95		2,113.74	/
			Acceptable	
		/		
		//		
		//		1

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THEAN (HP. 96623655) ENG TECH, CAE MIMI / AM SAE-A MSAAA/Accident Damage Appraiser

Page 1/3

Qualified Automobile Accident Damage Appraisers/Loss Adjusters 601, Choa Chu Kang Street 62, # 04-07, Singapore 680601 E-mail Address: aasschee@gmail.com

ail Address: aasschee@gmail.con Mobile Number: 96623655 RCB No. 43037800M

### ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No:

**GBB 6973T** 

Attachment to report no. TP/0004/02/2023

	REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
R	Replacement Of Damaged Panels/Parts and Labour Charges S\$ Price		Conditions	S\$ Price
01.	LABOUR CHARGES  Labour charges - R & R rear cargo bed	1,000.00	LUMP SUM REPAIR  Necessary  Reason being:	800,00
02.	Labour charges - R & R seat assy	100.00	To crane lift to remove and refit rear cargo bed assy to facilitate repair.  Necessary	80.00
			Reason being:  01. To remove and refit seat assy and etc. to facilitate the repair to the front cabin rear end panel.	
03.	Labour charges - Panel beating	750,00	Necessary  Reason being:  01. To straighten chassis frames where necessary, repair and reshape front cabin rear end panel, rear cargo bed and other affected areas.	500.00
04.	Labour charges - Spray Painting	1,000.00	Necessary  1. To respray paint on chassis frames (Black), rear cargo bed tailgate cover and LH side board, front cabin rear end panel and other affected areas.	800.00
05.	Labour charges - Anti rust proofing	80,00	Necessary Reason being: 01. To apply/respray anti rust proofing.	50.00
06.	Labour charges - Lighting system	30,00	Necessary Reason being: 01. To check wiring and lighting system.	30,00
		2,960.00		2,260.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUMN (HP. 96623655) ENG TECH, CAE MIMI / AM SAE-A MSAAA/Accident Damage Appraiser

Page 2/3

Qualified Automobile Accident Damage Appraisers/Loss Adjusters
601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@gmail.com
Mobile Number: 96623655

RCB No. 43037800M

#### ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No:

**GBB 6973T** 

Attachment to report no. TP/0004/02/2023

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS		
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price	
CARRIED FORWARD FROM PAGE 1/3				
Replacement of damaged panels/part	4,769.95		2,113.74	
CARRIED FORWARD FROM PAGE 2/3				\$1430
Labour Charges	2,960.00		2,260.00	<del>\$1730</del>
	7,729.95		4,373.74	\$3843-74
				\$ 3543.74
			LUMP SUM	77 5
			3,500.00	\$2834.99
				≈\$2800.00

NOTE:

Please refer to our recommendations of S\$ 4,373.74.

In our opinion, the vehicle can be repaired at a Lump Sum of S'pore Dollars: Eleven Thousand Only

 $(S$4,373.74 \times 20\% (S$874.75) = 3,498.99)$ 

### LUMP SUM CONTRACT

In view of the fact that the repairer has been offered a reduced budget to complete the repair. (TOTAL REVISED LESS ANOTHER 20%), the repairer should be entitled to exercise some discretion to complete the repair.

- a. To replace with New Parts (Genuine or Non Genuine Parts)
- b. To replace with Second Hand Parts (Imported or local Used Parts)
- c. To repair

The repairer would repair the vehicle to the entire satisfaction of the owner and in 'road worthy' condition.

The above terms and condition for the LUMP SUM REPAIR CONTRACT (Accident-Damaged Vehicle) is in line with the circular through a referendum from the Singapore Automobile Appraisers Association dated 25 May 2004,

Please find enclosed

- Letter from the Singapore Automobile Appraisers Association dated 25 May 2004
- Letter from The General Insurance Association Of Singapore dated 28 June 2004.
- Letter from the General Insurance Association Of Singapore dated 08 September 200
- The New Paper reply from NTUC Income dated 19 September 2003.

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655) ENG TECH, CAE MIMI / AM SAE-A MSAAA/Accident Damage Appraiser

Page 3/3

K24.119499

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, #04-07, Singapore 680601

E-mail Address: aasschee@gmail.com

Mobile Number: 96623655 RCB No. 43037800M

Date: 23 February 2023

OFFICIAL RECEIPT No. TP/0004/02/2023

Received from:

41. 1,

Ong Thye @ Ong Thai

c/o Kuo Li Auto Workshop

The sum of Dollars:

Six Hundred And Ninety Eight Only.

Being payment of:

Invoice Number: TP/0004/02/2023

Vehicle Number: GBB 6973T

S'pore Dollars:

698.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAY (HP 96623655) ENG TECH, CAE MIMI / AM SAE-A MSAAA/Accident Damage Appraiser