



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 6973T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR CARGO BED TAILGATE COVER	DENTED	2,286.32	2,286.32
2	REAR TAILLAMPS @\$267.30	REUSE	534.60	-
2	REAR TAILLAMP PANELS @\$124.33	TO REPAIR SEE LABOUR	248.66	-
2	REAR NUMBER PLATE LAMPS @\$139.00	REUSE	278.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	845.37	-
1	AIR DUCT	CRACKED	512.00	512.00
	LESS 25% DISCOUNT		-	-699.58
			4,704.95	2,098.74
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	REUSE	50.00	-
1	REAR CARGO BED TAILGATE '70KM/H' STICKER (SN)	NECESSARY	15.00	15.00
			65.00	15.00
<u>LABOUR</u>				
	R & R REAR CARGO BED - TO CRANE LIFT TO REMOVE AND REFIT REAR CARGO BED ASSY TO FACILITATE REPAIR.		1,000.00	400.00
	R & R SEAT ASSY - TO REMOVE AND REFIT SEAT ASSY AND ETC. TO FACILITATE THE REPAIR TO THE FRONT CABIN REAR END PANEL.	NOT NECESSARY	100.00	-
	PANEL BEATING - TO STRAIGHTEN CHASSIS FRAMES WHERE NECESSARY, REPAIR AND RESHAPE FRONT CABIN REAR END PANEL, REAR CARGO BED AND OTHER AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP PANELS AND REAR END PANEL.		750.00	500.00
	SPRAY PAINTING - TO RESPRAY PAINT ON CHASSIS FRAMES (BLACK), REAR CARGO BED TAILGATE COVER AND LH SIDE BOARD, FRONT CABIN REAR END PANEL AND OTHER AFFECTED AREAS.		1,000.00	500.00
	ANTI RUST PROOFING - TO APPLY / RESPRAY ANTI RUST PROOFING.	NOT NECESSARY	80.00	-

Report Ref No. CS3/LPC23001660/Wwy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LIGHTING SYSTEM - TO CHECK WIRING AND LIGHTING SYSTEM.		30.00	30.00
			2,960.00	1,430.00
GRAND TOTAL			7,729.95	3,543.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS3/LPC23001660/Wwy3e2-1

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.