



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23003305/Kny3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	05/07/2023
HEMMANT ROADSINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 4927Y	Veh. Inspected	SLB 4151T
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/123	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	29/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AXIO (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NRE1610013858	Colour	METALLIC SILVER
Odometer	62222 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60R15	TOYO	4 mm
L/H Front Tyre	185/60R15	TOYO	4 mm
R/H Rear Tyre	185/60R15	TOYO	7 mm
L/H Rear Tyre	185/60R15	TOYO	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/09/2022	Inspection Date	30/03/2023
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	