

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23003315/KQP3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT102753		
Claimant Vehicle No :	SHD5297L	Insured Vehicle No :	GBD896L		
Date of Loss:	24/03/2023	Nature of Claim:	TP	Claim No:	M2302032

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5297L	Engine No:	2ZR2B73630
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU403076723
Reg. Date:	15/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,033.77	5,851.55	2,182.22	27.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	930.00	3,640.00	79.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,603.77	6,781.55	5,822.22	46.19
Approved Total (Overridden) (S\$)		5,450.00		
Nett Amount (S\$)	12,603.77	5,450.00	7,153.77	56.76

INSPECTION

Date of Assignment:	30/03/2023		
Date Inspected:	28/03/2023	Inspected At:	Trans cab Auto Service - Ang Mo Kio (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5297L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FRONT BUMPER	Cracked	653.31 FL	*653.31 FL
2	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	100.17 FL	*- FL
3	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Repair	902.16 FL	*- FL
4	1		*SUPPORT ,FRONT BUMPER SIDE ,LH	Distorted	100.49 FL	*100.49 FL
5	1		*STAY SUB-ASSY ,FRONT BUMPER ,LH	Serviceable	59.85 FL	*- FL
6	1		*LINER ,FRONT FENDER ,LH	Distorted	255.36 FL	*255.36 FL
7	1		*FENDER SUB-ASSY ,FRONT LH	Bent	1,236.69 FL	*1,236.69 FL
8	1		*FRONT FENDER EMBLEM LH	Necessary	68.88 FL	*68.88 FL
9	1		*RIM	Dented	1,995.11 FL	*1,995.11 FL
10	1		*LAMP ASSY ,FOG ,LH	Serviceable	1,200.78 FL	*- FL
11	1		*UNIT ASSY ,HEADLAMP ,LH	Mtg Cracked	3,325.56 FL	*3,325.56 FL
12	1		*FENDER LINER CLIP	Necessary	65.00 FS	*65.00 FS
13	1		*TYRE	Serviceable	350.00 FS	*- FS
14	1		*FRT BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
15	1		*FRT LH BUMPER BRACKET CLIP	Not Necessary	65.00 FS	*- FS
16	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,508.36	7,760.40
- List Item Discount on L Items 25.00/25.00% (S\$)	2,474.59	1,908.85
Total Parts (S\$)	8,033.77	5,851.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	600.00	30.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	440.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			4,570.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >