

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23003322/HWY3M4**Date:** 24/04/2023**REFERENCE**

Insured/Claimant:	LIEW MING HUA LUCAS	Policy No:	SP2004848774
Date of Loss:	29/03/2023	Nature of Claim:	OD
		Claim No:	202332006635

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ4584L		
Make & Model:	HYUNDAI AVANTE, 1.6 AT ABS D/AB 2WD 4DR (A)	Engine No:	G4FC9U798776
Reg. Date:	16/03/2010 (Man. Year: 2009)	Chassis No:	KMH DU41BMAU963632
Colour:	Silver	Odometer:	97296 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$19,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	LAUFENN 5 mm	Rear Left Side:	LAUFENN 5 mm
Front Right Side:	LAUFENN 5 mm	Rear Right Side:	LAUFENN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,800.90	3,117.30	1,683.60	35.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,600.00	610.00	27.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,010.90	4,717.30	2,293.60	32.71
Approved Total (Overridden) (S\$)		3,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,410.90	2,700.00	3,710.90	57.88
+ GST 8.00/8.00% (S\$)	512.87	216.00	296.87	57.88
Nett Amount (S\$)	6,923.77	2,916.00	4,007.77	57.88

INSPECTION

Date of Assignment:	29/03/2023 Present Location:	Shu Fatt Auto Works (HQ)
		SHU FATT AUTO WORKS
Date Inspected:	29/03/2023 Inspected At:	BLK 1009, BUKIT MERAH LANE 3 #01-90
		SINGAPORE 159723
Estimated Period of Repair:	5.0 days	

Adjuster: Edward**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	143	HYUNDAI AVANTE 1.6 AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ4584L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet (WCP)	Buckled	550.00 F	*550.00 F
2	1		*Front bonnet insulator (WCP)	Not Necessary	105.00 F	*- F
3	12		*Front bonnet insulator clips (WCP)	Not Necessary	30.00 F	*- F
4	1		*Front bonnet lock (WCP)	Not Necessary	30.00 F	*- F
5	2		*Front headlights (WCP)	Cracked	600.00 F	*600.00 F
6	1		*Front headlights holders 2PIECES (WCP)	Cracked (1Piece Only)	50.00 F	*25.00 F
7	1		*Front grille (WCP)	Cut	170.00 F	*170.00 F
8	1		*Front grille emblem (WCP)	Necessary	38.00 F	*38.00 F
9	8		*Front grille clips (WCP)	Necessary	20.00 F	*20.00 F
10	2		*Front fenders (WCP)	Bent	360.00 F	*360.00 F
11	2		*Front fenders cowlings (WCP)	Not Necessary	100.00 F	*- F
12	20		*Front fenders cowlings clips (WCP)	Not Necessary	50.00 F	*- F
13	1		*Front support panel (WCP)	Bent	480.00 F	*480.00 F
14	1		*Front bumper (WCP)	Cut	240.00 F	*240.00 F
15	1		*Front bumper reinforcement (WCP)	Bent	120.00 F	*120.00 F
16	1		*Front bumper foam (WCP)	Cracked	70.00 F	*70.00 F
17	2		*Front bumper brackets (WCP)	Not Necessary	36.00 F	*- F
18	16		*Front bumper clips (WCP)	Necessary	40.00 F	*40.00 F
19	2		*Front bumper side retainers (WCP)	Necessary	30.00 F	*30.00 F
20	1		*Front bumper lower grille (WCP)	Cut	50.00 F	*50.00 F
21	8		*Front bumper lower grille clips (WCP)	Not Necessary	20.00 F	*- F
22	1		*Front bumper air con condenser (WCP)	Not Necessary	550.00 F	*- F
23	1		*Front aircon fan (WCP)	Not Necessary	550.00 F	*- F
24	1		*Front number plate	Bent	55.00 FS	*45.00 FS
25	1		*Coolant	Not Necessary	28.00 FS	*- FS
26	1		*L/FOG LAMP (NPA)	Not Necessary	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	4,372.00	2,838.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	428.90	279.30
Total Parts (\$\$)	4,800.90	3,117.30

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To knock frt inner panel, frt lower panel, frt side panel, left frt wheel house, right frt wheel house, frt lower member, renew frt bonnet, frt support panel, frt fenders, frt grille, frt lights, frt bumper & assembly.	New	900.00	600.00
2	To respray damaged parts.	New	1,050.00	1,000.00
3	to remove, replace aircon condenser and fill in aircon freon & compressor oil.	New	260.00	0.00
Gross Labour Cost (\$\$)			2,210.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >