

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Mindef ref: CY22/MID34464/160323/0052

LKK ref: CC2/MIDA23003324/Wp Date: 28/04/2023

HQ TRANSPORT COMMAND

Attn: Maj Edwin

Dear Sir/Madam

APPRAISAL OF DAMAGED VEHICLE BEFORE REPAIRS: GBB220Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/3/2023 at the premises of M/s YONG SENG MOTOR and have the following to report:-


- A) The inspection was conducted on a "Without Prejudice" basis.
- B) The repair estimate was not presented at the time of inspection.
- C) Enclosed please find damaged vehicle photographs.
- D) The estimated repair cost of the damaged vehicle is in the region of \$3,000.00-\$4,000.00.

Market Value	: S\$	(est)
LTA Reimbursement Value	: S\$	(est)
Nett Value	: S\$	(est)

Description of Damage:

The vehicle sustained damages at the

RIGHT REAR PORTION.



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MOHAMMAD AKID

Licensed Appraiser