



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE
HQ TRANSPORT COMMAND
KRANJI CAMP 3
151 CHOA CHU KANG WAYSINGAPORE 688248

Ref: CC2/MIDA23003325/Rpq2

Date: 06/06/2023

Code: MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 46357 / GBF8459C	Veh. Inspected	SLM 932A
Policy No.		Coverage (\$)	0.00
Claim No.	CY22/MID46357-GBF8459C/210323/0053	Excess (\$)	0.00
Assign From		Assign Date	30/03/2023

2. Vehicle Particulars & Condition

Make & Model	NISSAN PULSAR 1.2L DIG-T	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKDDAC13U0098503	Colour	GREY
Odometer	53484 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50Z R17	FALKEN	6 mm
L/H Front Tyre	205/50Z R17	FALKEN	6 mm
R/H Rear Tyre	205/50Z R17	FALKEN	6 mm
L/H Rear Tyre	205/50Z R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/03/2023	Inspection Date	26/04/2023
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 932A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	GROMMET BUMPER @\$3.00 (N)	NECESSARY	6.00	6.00
1	GROMMET RH COMB LAMP (N)	NOT NECESSARY	5.40	-
1	COMB LAMP RH (N)	NOT NECESSARY	514.60	-
4	CLIP BUMPER @\$1.50 (N)	NECESSARY	6.00	6.00
1	BRKT REAR RH (N)	NOT NECESSARY	81.60	-
	LESS 20% DISCOUNT		-122.72	-2.40
			490.88	9.60
<u>SPECIAL NETT ITEMS</u>				
1	CLIP C/LAMP (SN)	NECESSARY	7.30	7.30
1	SUNDRIES (SN)	NECESSARY	20.00	20.00
1	205/50ZR17 FALKEN FK510 RH REAR (SN)	NOT NECESSARY	250.00	-
1	SEN UNIT-TIRE P (SN)	NECESSARY	178.90	178.90
1	ALUMINIUM WHEEL RH REAR (SN)	SCRATCHED	903.20	903.20
			1,359.40	1,109.40
<u>LABOUR</u>				
	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS,INTERROGATION & REPROGRAM MODULE WITH CONSULT.		240.00	240.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	CHECK WHEEL ALIGNMENT ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE .		108.00	108.00
	REPAIR REAR BUMPER ,RH REAR FENDER .		900.00	585.00
	S/PAINT REAR BUMPER AND RH REAR FENDER .		750.00	500.00
	RENEW RH REAR S/RIM AND CONDUCT WHEEL BALANCING .		15.00	15.00
	RENEW RH REAR S/RIM TPS SENSOR .		120.00	120.00
	R/I REVERSE SENSOR TO ASSIST REPAIR .		55.00	55.00
			2,308.00	1,743.00
GRAND TOTAL			4,158.28	2,862.00

Report Ref No. CC2/MIDA23003325/Rpq2



RECOMMENDED COST OF REPAIRS			2,862.00
-----------------------------	--	--	----------

Report Ref No. CC2/MIDA23003325/Rpq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 932A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 932A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 932A

RE-INSPECTION

