

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III23003327/KQY3E2**Date:** 19/07/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD Policy No: D18MFL0003414

Date of Loss: 05/03/2023

Nature of Claim: OD

Claim No: MFL2023D0005727

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE7165T**
 Make & Model: MAZDA BIANTE, 2.0 BIANTE 5-DOOR WAGON
 SP.6E (A) Engine No: PE30870178
 Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: JM6CC1071G0109253
 Colour: Metallic Black Odometer: 180783 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: S\$67,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Goodyear 7 mm Rear Left Side: RAPID 8 mm
 Front Right Side: Hankook 7 mm Rear Right Side: RAPID 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,246.29	2,853.10	2,393.19	45.62
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,830.00	1,140.00	690.00	37.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,087.29	4,004.10	3,083.19	43.50
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	7,087.29	2,504.10	4,583.19	64.67
+ GST 8.00/8.00% (S\$)	566.98	200.33	366.65	64.67
Nett Amount (S\$)	7,654.27	2,704.43	4,949.84	64.67

INSPECTION

Date of Assignment: 30/03/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)
 Date Inspected: 30/03/2023 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)
 205 Braddell Road
 Singapore 579701
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2023)
Parts:	M1-MPV	MAZDA BIANTE 2.0 BIANTE 5-DOOR WAGON SP.6E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE7165T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP	Serviceable	2,888.73 FL	*- FL
2	1		*LH HEADLAMP SIDE GARNISH	Cut	635.52 FL	*635.52 FL
3	1		*FRONT LH QUOTER GLASS	Cut	439.13 FL	*439.13 FL
4	1		*LH SIDE MIRROR GLASS	Cut	118.00 FL	*118.00 FL
5	1		*LH SIDE MIRROR COVER	Missing	100.98 FL	*100.98 FL
6	1		*LH SIDE MIRROR ASSY	Broken	387.80 FL	*387.80 FL
7	1		*FRONT LH DOOR	Bent	1,342.34 FL	*1,342.34 FL
8	1		*FRONT LH DOOR BLACK MOULDING	Necessary	72.83 FL	*72.83 FL
9	1		*FRONT LH DOOR STICKER 1	Necessary	25.04 FL	*25.04 FL
10	1		*FRONT LH DOOR STICKER 2	Necessary	38.27 FL	*38.27 FL
11	1		*FRONT LH DOOR HANDLE (CHROME)	Dented	236.17 FL	*236.17 FL
12	1		*FRONT LH DOOR UPPER HINGE	Repair	49.56 FL	*- FL
13	1		*FRONT LH DOOR LOWER HINGE	Repair	53.19 FL	*- FL
14	1		*FRONT LH FENDER (REPAIR) (NPA)	Repair	-	*- FL
Supplementary #1						
15	1		*FRONT SIGNAL LAMP ASSY LH	Cracked	170.30 FL	*170.30 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					6,557.86	3,566.38
- List Item Discount on L Items 20.00/20.00% (S\$)					1,311.57	713.28
Total Parts (S\$)					5,246.29	2,853.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To knock & straighten on accident area, to remove & refit Left damage parts.	New	800.00	500.00
2	To putty & respray on Left damage area.	New	800.00	500.00
3	To check wiring.	New	50.00	20.00
4	To remove & refit Front Lh Door trim, door glass, window regulator, door lock to assist work load.	New	80.00	60.00
5	To remove & refit front Lh quarter glass.	New	100.00	60.00
Gross Labour Cost (\$\$)			1,830.00	1,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >