

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23003331/AYA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : SLB7706Z**Insured Vehicle No :** GBM658K

Date of Loss: 27/03/2023

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLB7706Z**

Make & Model: TOYOTA WISH, 1.8 X CVT (A)

Engine No: 2ZR1700344

Reg. Date: 21/04/2016 (Man. Year: 2016)

Chassis No: ZGE206029264

Colour: Silver

Odometer: 100431 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,956.57	4,043.70	3,912.87	49.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,060.00	1,290.00	54.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,306.57	5,103.70	5,202.87	50.48
Approved Total (Overridden) (S\$)		4,050.00		
Nett Amount (S\$)	10,306.57	4,050.00	6,256.57	60.70
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/03/2023

Date Inspected: 29/03/2023 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7706Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	760.20 FL	*545.00 FL
2	10		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
3	1		*FRONT BUMPER GRILLE (LOWER)	Not Necessary	296.20 FL	*- FL
4	1		*FRONT BUMPER ENFORCEMENT	Not Necessary	306.20 FL	*- FL
5	1		*FRONT BUMPER INSULATOR	Cracked	190.20 FL	*190.20 FL
6	2		*FRONT BUMPER O/S & N/S RETAINER	Damaged	212.20 FL	*90.00 FL
7	2		*FRONT BUMPER O/S & N/S FOG LAMP GARNISH	Not Necessary	177.00 FL	*- FL
8	2		*FRONT BUMPER O/S & N/S FOG LAMP GARNISH COVER	Not Necessary	245.20 FL	*- FL
9	1		*FRONT GRILLE	Cracked	586.20 FL	*327.00 FL
10	1		*FRONT GRILLE CLIPS (6 PCS)	Necessary	48.00 FS	*20.00 FS
11	1		*FRONT GRILE TOP COVER	Deformed	93.20 FL	*93.20 FL
12	1		*SET FRONT GRILE TOP COVER CLIP	Necessary	30.00 FS	*20.00 FS
13	1		*FRONT EMBLEM	Necessary	130.40 FL	*130.40 FL
14	1		*FRONT BONNET	Dented	1,267.50 FL	*869.00 FL
15	1		*FRONT BONNET HEAT SHIELD INSULATOR	Not Necessary	494.10 FL	*- FL
16	8		*FRONT BONNET HEAT SHIELD INSULATOR CLIPS	Not Necessary	64.00 FL	*- FL
17	2		*FRONT O/S & N/S BONNET HINGES	Not Necessary	141.60 FL	*- FL
18	1		*FRONT O/S & N/S HEAD LAMP	N/S Cracked	3,049.60 FL	*1,524.80 FL
19	2		*FRONT O/S & N/S FENDER (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*FRONT N/S FENDER WHEEL GUARD	Not Necessary	207.30 FL	*- FL
21	8		*FRONT N/S FENDER WHEEL GUARD CLIPS	Not Necessary	64.00 FS	*- FS
22	1		*FRONT REG NUMBER PLATE	Dented	45.00 FS	*30.00 FS
23	1		*FRONT REG NUMBER PLATE BRACKET	Deformed	29.00 FS	*29.00 FS
24	1		*FRONT BONNET LOCK	Not Necessary	97.00 FL	*- FL
25	1		*FRONT BRACE PANEL	Bent	95.00 FL	*95.00 FL
26	1		*FRONT AIR-CON CONDENSER	Warped	1,801.00 FL	*1,355.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,510.10	5,348.60
- List Item Discount on L Items 25.00/25.00% (S\$)	2,553.53	1,304.90
Total Parts (S\$)	7,956.57	4,043.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE FRONT PORTION ,STRAIGHTEN & WELDING	New	1,000.00	500.00
2	TO SPRAY PAINTING	New	900.00	500.00
3	TO CHECK FOR FAULT CODE AND RESET ELECTRICAL SYSTEM	New	100.00	0.00
4	TO CHECK WIRING	New	100.00	30.00
5	TO RESEAL ANTI RUST	New	100.00	30.00
6	TO RENEW & REFIX AIRCON CONDENSER ,VACUUM & REFILING GAS	New	150.00	0.00
Gross Labour Cost (S\$)			2,350.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >