Adjuster Report 5/9/23, 3:23 PM

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI23003336/KVP3E2

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

09/05/2023 Date: Singapore 079909

**REFERENCE** 

SEOW KIAN JOO Insured/Claimant: Policy No: DMPCSNW00246842200

Date of Loss: 27/03/2023 Nature of Claim: Claim No: SNM23D202304/C01/KHONGLH

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SCM1818Y** 

BMW X3, 2.0 xDrive28i (F25) (A) Make & Model: Engine No: B1260566N20B20A 16/05/2014 (Man. Year: 2013) Chassis No: WBAWX92040L999693 Reg. Date:

Colour: White Odometer: 121615 km

1997 cc **Engine Capacity:** Market Value/New Car

S\$58,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

**CONDITION OF TYRES** 

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18 Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		29,787.90	16,176.60	13,611.30	45.69
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,500.00	241.50	1,258.50	83.90
Paintwork Labour		986.28	418.43	567.85	57.57
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	32,274.18	16,836.53	15,437.65	47.83
	Approved Total (Overridden) (S\$)		13,450.00		
	(S\$)	32,274.18	13,450.00	18,824.18	58.33
	+ GST 8.00/8.00% (S\$)	2,581.93	1,076.00	1,505.93	58.33
	Nett Amount (S\$)	34,856.11	14,526.00	20,330.11	58.33

**INSPECTION** 

Date of Assignment: 30/03/2023

BLK 10 #01-20 SIN MING IND EST SEC C

Date Inspected: 31/03/2023 Inspected At: SINGAPORE 575645

Repairer: Ding Auto Pte Ltd (HQ)

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report 5/9/23, 3:23 PM

### **REPAIR DETAILS**

Reference

Version: 1.0 (Last Synchronised: 09 May 2023) Part Source: MRM-SG

Parts: M1-SUV BMW X3 2.0 xDrive28i (F25) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCM1818Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS - TOTAL AMOUNT		27,977.90 F	*14,366.60 F
<u>Sup</u>	<u>pleme</u>	entary #1				
2	1		*FRONT BUMPER NOZZLE JET LH	Cracked	140.00 F	*140.00 F
3	1		*FRONT BUMPER NOZZLE CAP LH	Missing	70.00 F	*70.00 F
4	1		*FRONT BUMPER SUPPORT ADAPTER RH	Bent	220.00 F	*220.00 F
5	1		*FRONT BUMPER SUPPORT ADAPTER LH	Bent	220.00 F	*220.00 F
6	1		*FRONT BUMPER PARKING SENSOR HARNESS WIRE CPL	Cut	360.00 F	*360.00 F
7	1		*HEADLAMP - REPAIR KIT LED MODULE - HIGH BEAM	Cracked	400.00 F	*400.00 F
8	1		*HEADLAMP - REPAIR KIT LED MODULE - LOW BEAM	Cracked	400.00 F	*400.00 F
F=Fra	anchise	part.		P		
				Total Parts (S\$)	29,787.90	16,176.60
				,		

Report was unsubmitted during this print-out.

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
<u>Pair</u>	ntwork Labour							
1	Total Paint Labour	New	800.00	245.00				
2	Total Paint Materials	New	186.28	173.43				
Lab	our Items							
3	Total Panel/Mechanical Labour	New	1,500.00	241.50				
		Gross Labour Cost (S\$)	2,486.28	659.93				
Report was unsubmitted during this print-out.								

< END OF ESTIMATES >