



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 2351X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER	BUCKLED / DENTED	498.36	498.36
1	FRT BUMPER RETAINER -LH	SERVICEABLE	59.84	-
1	FRT HEADLAMP -LH	CUT	967.24	967.24
1	FRT FENDER -LH	TO REPAIR SEE LABOUR	489.74	-
	LESS 25% DISCOUNT		-503.80	-366.40
			1,511.38	1,099.20
	<b><u>LABOUR</u></b>			
	TO PULL ,KNOCK ON ACCIDENT PORTION & CHARGE ABOVE PART.INCLUSIVE OF THE REPAIR OF FRT FENDER -LH.		480.00	300.00
	TO SPRAY PAINT ON FRT ACCIDENT PORTION .		580.00	400.00
	TO CHECK ELECTRICAL WIRING SYSTEM. }		60.00	20.00
	TO CHECK ELECTRICAL AND FOCUS HEADLAMP .}		60.00	-
			1,180.00	720.00
<b>GRAND TOTAL</b>			<b>2,691.38</b>	<b>1,819.20</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,450.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO23003339/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.