



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3345Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	SCRATCHED	798.40	474.00
2	FRONT BUMPER SIDE LAMP @\$121.30	NOT NECESSARY	242.60	-
2	FRONT BUMPER FOGLAMP C/W BRACKET @\$294.70	NOT NECESSARY	589.40	-
2	FRONT BUMPER FOGLAMP GARNISH @\$115.40	NOT NECESSARY	230.80	-
1	FRONT BUMPER NUMBER PLATE HOLDER	NOT NECESSARY	110.60	-
1	FRONT BUMPER LOWER LIP	NOT NECESSARY	289.70	-
2	FRONT BUMPER SIDE RETAINER @\$46.80	NOT NECESSARY	93.60	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	695.90	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	176.40	-
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	198.50	-
2	FRONT BUMPER SIDE BEAM @\$97.90	NOT NECESSARY	195.80	-
1	FRONT BUMPER LOWER BEAM	NOT NECESSARY	258.70	-
1	FRONT BUMPER TOP RUBBER	NOT NECESSARY	69.40	-
1	FRONT ENGINE UNDER COVER	NOT NECESSARY	194.60	-
1	CENTER GRILLE	CUT / SCRATCHED	490.20	490.20
1	CENTER GRILLE LOGO	NECESSARY	67.40	67.40
1	HEAD LAMP LH	NOT NECESSARY	1,198.80	-
1	HEAD LAMP LOWER BRACKET LH	NOT NECESSARY	89.60	-
	LESS 20% DISCOUNT		-1,198.08	-206.32
			4,792.32	825.28
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	40.00
1	SET FRONT ENGINE UNDER COVER CLIP (SN)	NOT NECESSARY	80.00	-
1	SET CENTER GRILLE CLIP (SN)	NECESSARY	60.00	20.00
			220.00	60.00
<u>LABOUR</u>				
	PANEL BEATING ON AFFECTED AREAS.		2,800.00	200.00
	SPRAY PAINTING ON AFFECTED AREAS.		2,100.00	200.00
	TO CHECK WIRING AND HEADLAMP FUNCTIONS.		150.00	30.00

Report Ref No. CS/INC23003347/Sqy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING.	NOT NECESSARY	240.00	-
			5,290.00	430.00
GRAND TOTAL			10,302.32	1,315.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,050.00

Report Ref No. CS/INC23003347/Sqy3e2

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.