

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Loo Pac
Xin Yu

Vehicle No. GBJ3523L

TOYOTA DYNA

JTFAT35Y40K212021

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR NUMBER PLATE BRACKET <i>Best.</i>		160.40	✓
2	TAILLAMP @255.40 <i>3 new</i>		510.80	+
3	TAILLAMP PANEL @185.5		371.00	+
4	TAILGATE <i>Dented.</i>		1482.50	✓
5	TAILGATE HINGE @65.50 <i>2 pieces Best.</i>		262.00	131.
6	TAILGATE LOWER LOCK @194.30 <i>new</i>		388.60	+
7	TAILGATE LOWER PANEL <i>Repair</i>		495.60	+
8	STOPPER BRACKET @153.20 <i>new</i>		306.40	+
		1773.90		
		133042		
		less	25%	25%
			3977.30	
			994.33	
			2982.98	
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE <i>Best.</i>		30.00	✓
2	REVERSE SENSOR <i>Dand</i>		280.00	200.
3	70KM/H <i>new</i>		15.00	✓
4	STICKERS		280.00	120.
5	STOPPER @40 <i>new</i>		80.00	+
		365		
Total Parts			685.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
LABOUR			
1	PANEL BEATING	1000.00	300
2	SPRAY PAINTING	700.00	400
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	100.00	40
5	TO REMOVE REVERSE SENSOR	100.00	50.
	Labour Total :	1950.00	820
TOTAL (PARTS & LABOUR):		5617.98	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 2515.42
L/S: 2K
030up