

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Loo Pac
Xin Yu.

Vehicle No. GBJ3523L

TOYOTA DYNA

JTFAT35Y40K212021

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT		
PARTS (LIST ITEMS)							
1	REAR NUMBER PLATE BRACKET <i>Best.</i>	1773.90 133042		160.40	✓		
2	TAILLAMP @255.40 <i>} ne nu</i>			510.80	+		
3	TAILLAMP PANEL @185.5			371.00	+		
4	TAILGATE <i>Dented</i>			1482.50	✓		
5	TAILGATE HINGE @65.50 <i>2 pieces Best.</i>			262.00	131.		
6	TAILGATE LOWER LOCK @194.30 <i>ne nu</i>			388.60	+		
7	TAILGATE LOWER PANEL <i>Repair</i>			495.60	+		
8	STOPPER BRACKET @153.20 <i>not nu</i>			306.40	+		
					3977.30		
			less	25%	994.33	25%	
				2982.98			
SPECIAL NETT ITEMS							
1	REAR NUMBER PLATE <i>Best.</i>	365		30.00	✓		
2	REVERSE SENSOR <i>Damaged</i>			280.00	200.		
3	70KM/H <i>} ne nu</i>			15.00	✓		
4	STICKERS			280.00	120.		
5	STOPPER @40 <i>ne nu</i>			80.00	+		
Total Parts				685.00			

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
LABOUR			
1	PANEL BEATING	1000.00	800
2	SPRAY PAINTING	700.00	400
3	WIRING	50.00	30
4	TO APPLY TUFF COAT	100.00	40
5	TO REMOVE REVERSE SENSOR	100.00	50.
Labour Total :		1950.00	820
TOTAL (PARTS & LABOUR):		5617.98	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 2515.42
L/S: 2K
030up