



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 291H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	SQUASHED	482.30	482.30
2	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	756.00	-
2	REAR BUMPER REVERSE SENSOR HOLDER	NECESSARY	24.00	24.00
1	REAR BUMPER REFLECTOR RH	FRACTURED	58.40	58.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	379.20	-
2	REAR BUMPER REINFORCEMENT BRACKET RH / LH	NOT NECESSARY	130.00	-
2	REAR BUMPER SIDE RETAINER RH / LH	NECESSARY	207.00	207.00
	LESS 25% DISCOUNT		-	-192.93
			2,036.90	578.77
<u>SPECIAL NETT ITEMS</u>				
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
			385.00	35.00
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH AND REAR FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS.		800.00	500.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,000.00	600.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		120.00	30.00
			2,000.00	1,160.00
GRAND TOTAL			4,421.90	1,773.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CS3/LPC23000444/Tny3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.