

PAR Automotive Consultancy

Regn. No: 52986974L

Mailing Address : Blk 310 Shunfu Road #07-213, Singapore 570310. Tel : 645 31173, Fax : 645 36131.

Report No: 0019-23-SHLM

10 March 2023

Ngui Yong Siang
112 Bukit Batok West Ave 6 #08-146
Singapore 650112

INVOICE No. **0019-23-SHLM**


Vehicle No. **SGU291H**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$539.00
Total amount payable		<u>\$539.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Mailing Address : Blk 310 Shunfu Road #07-213, Singapore 570310. Tel : 645 31173, Fax : 645 36131.

Report No: 0019-23-SHLM

10 March 2023

ACCIDENT VEHICLE SURVEY REPORT

Ngui Yong Siang
112 Bukit Batok West Ave 6 #08-146
Singapore 650112

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SGU291H	<i>Odometer:</i>	25303km
<i>Make & Model:</i>	Toyota Corolla Altis	<i>Colour:</i>	Black
<i>Chassis number:</i>	MR053REH604599065	<i>Date of accident:</i>	10/01/2023
<i>Year of Regn.:</i>	23/10/2019	<i>Date inspected:</i>	17/01/2023
<i>Repairer at:</i>	Sin Heng Long Motor Work	<i>Date inspected (After Repair):</i>	19/01/2023
	Blk 5032 Ang Mo Kio Ind Pk 2 #01-287/305		
	Singapore 569535		

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	5mm/Yokohama	5mm/Yokohama	205/55R16
<i>Rear:</i>	5mm/Yokohama	5mm/Yokohama	205/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0019-23-SHLM

Vehicle No: SGU291H

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear bumper	1	squashed	482.30	482.30 ✓
Rear bumper reverse sensor	2	shorted	756.00	756.00 ✗ nn
Rear bumper reverse sensor holder	2	necessary	24.00	24.00 ✓
Rear bumper reflector RH	1	fractured	58.40	58.40 ✓
Rear bumper reinforcement	1	bent	379.20	379.20 ✗ nn
Rear bumper reinforcement bracket RH/LH	2	bent	130.00	130.00 ✗ nn
Rear bumper side retainer RH/LH	2	necessary	207.00	207.00 ✓
771.70		<i>Subtotal before discount</i>	2,036.90	2,036.90
-25%	<i>Percentage discount</i>	<i>0% and 25%</i>	0.00	509.23
578.77		Sub-total 1	2,036.90	1,527.68
Rear reverse sensor	1	shorted	350.00	300.00 ✗ nn
Rear bumper clip - set	1	necessary	35.00	35.00 ✓
35		<i>Subtotal before discount</i>	385.00	335.00
	<i>Percentage discount</i>	<i>0% and 0%</i>	0.00	0.00
		Sub-total 2	385.00	335.00
		Parts-total	2,421.90	1,862.68
LABOUR				
1. To straighten and panel beating rear fender RH and rear frame members To remove and refit above parts.			800.00	500.00 ✓
2. To putty, re-spray painting and polish affected areas.			1,000.00	750.00 600
3. To check and rectify wiring system.			80.00	50.00 30
4. To rust proof affected areas.			120.00	60.00 30
1160		Labour total	2,000.00	1,360.00
		Parts & Labour total	4,421.90	3,222.68

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$2,700.00

4

4 days

1773.77

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

L/S - 1419.01
= 1400























