



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 9508E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT BRAKE LEVER	SCRATCHED	118.50	45.00
1	CARBON AIR FILTER COVER	SCRATCHED	436.60	180.00
1	CARBON BATTERY COVER	NOT NECESSARY	301.25	-
1	CARBON DASHBOARD COVER	SCRATCHED	1,292.50	300.00
1	N/S CARBON FOOTREST FAIRING	SCRATCHED	373.10	160.00
1	CARBON FRONT FENDER	SCRATCHED	222.30	180.00
1	N/S CARBON FRONT LOWER FAIRING	SCRATCHED	276.55	140.00
1	O/S CARBON MID SIDE FAIRING	SCRATCHED	185.10	100.00
1	CARBON UNDER HEADLAMP FAIRING / WINGLET	CRACKED	316.40	120.00
1	HAND O/S GRIP	CUT	52.75	52.75
2	FRONT SIGNAL LAMP	NOT NECESSARY	108.80	-
2	FRONT UPPER FAIRING (O/S AND N/S)	CRACKED	470.20	300.00
1	HEADLAMP ASSY	SCRATCHED	1,253.60	680.00
2	L SHAPE VIEW MIRROR	SCRATCHED / MISSING	108.90	45.00
2	SIDE MIDDLE LOWER FAIRING (O/S AND N/S)	CRACKED	273.60	130.00
1	MAIN STAND	SERVICEABLE	181.10	-
1	PILLION BAR	TO REPAIR SEE LABOUR	203.55	-
1	N/S PILLION FOOT REST	NOT NECESSARY	44.80	-
1	N/S REAR CARBON PROTECTOR	SCRATCHED	74.40	74.40
1	N/S REAR SIDE FAIRING COVER	SCRATCHED / CRACKED	246.10	100.00
1	SIDE STAND	SCRATCHED	78.50	-
1	UNDER BELLY COVER	CRACKED	307.10	150.00
1	O/S BODY "YAMAHA" EMBLEM	NECESSARY	16.50	16.50
1	O/S FOOTREST REST PLATE	DENTED	81.35	70.00
1	FRONT GLOVE BOX COMPARTMENT O/S	SCRATCHED	36.00	36.00
1	FRONT BRAKE DISC	NOT NECESSARY	185.60	-
	LESS 10% DISCOUNT		-724.52	-287.97
			6,520.63	2,591.68

Report Ref No. CS3/SMR22011481/Svy3m4-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FORK ASSY (LOCAL REPAIR) (SN) LESS 10% DISCOUNT	BENT	1,306.70 -130.67	80.00 -
	LABOUR TO CHECK, PRESS AND STRAIGHTEN BODY FRAME BY SPECIALIST. TO APPLY PRIMER, TO PUTTY AND PAINT ACCIDENT AFFECTED AREAS. TO REMOVE DAMAGED PARTS, STRAIGHTEN AND KNOCK BRACKET AND REPLACE RECOMMENDED PARTS AND RE-ALIGNMENT BODY PARTS AFTER REPAIRS. INCLUSIVE OF THE REPAIR OF PILLION BAR.		1,176.03 350.00 500.00 500.00 1,350.00	80.00 100.00 100.00 200.00 400.00
GRAND TOTAL			9,046.66	3,071.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,450.00

Report Ref No. CS3/SMR22011481/Svy3m4-1

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.