



**SINGAPORE  
POLICE FORCE**



G/20221114/7030

2 of 2

**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

Report No. G/20221114/7030

cut near the heels area. My bike(FBQ9508E) was damaged badly after the incident. Refer to G/20221111/0145

<b>Subjects Involved</b>			
<b>Suspect</b>			
Person Name	TOH KHENG POH, JIMMY		
ID Type	NRIC NO	ID No	S1683207C
Gender	Male	Age	57-57
Race	Chinese	Language	English
Occupation	Taxi driver	Address	684D Woodlands Drive 73 #13-177 SINGAPORE 734684
Mobile No	91267306		
<b>Victim</b>			
Person Name	MUHAMMAD IMRAN BIN RAMLAN		
ID Type	NRIC NO	ID No	S9433503E
Gender	Male	Age	28
Race	Malay	Language	English
Occupation	Delivery man using motorised personal mobility aids/devices	Address	427 PASIR RIS DRIVE 6 #07-45 SINGAPORE 510427
Mobile No	91990979	Is Informant A Victim?	Yes
Person Name	MUHAMMAD IMRAN BIN RAMLAN (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 14/11/2022 11:42
Officer In-Charge Of Case:	Classification Of Case:

# TNECNIV SERVICES

Blk 495-E Tampines Street 43, #04-368 Singapore 524495 Tel : 97859520


To : Muhammad Imran Bin Ramlan  
Block 427 Pasir Ris Drive 6, #07-45  
Singapore 510427.

Date : 10/1/2023

Invoice No : TP/2022/00611

PARTICULARS	AMOUNT
<b>RE : <u>FBQ9508E</u></b>	
SURVEY FEE : \$	\$ 764.00
PHOTOGRAPHS : \$	
TRANSPORT : \$	
RESURVEY : \$	
<b>TOTAL DOLLARS : Seven Hundred and Sixty-Four only.</b>	

For TNECNIV SERVICES



LICENSED APPRAISER

E.&O.E.

# TNECNIV SERVICES

Blk 495-E Tampines Street 43, #04-368 Singapore 524495. Tel : 97859520

Reg.No. : 53436440C Insurance Loss Adjuster Licensed Appraiser

( Member Of Singapore Automobile Appraisers Association )

## AUTOMOBILE INSPECTION REPORT

m/s	Muhammad Imran Bin Ramlan	Date :	10/1/2023
	Block 427 Pasir Ris Drive 6, #07-45	Our Ref :	TP/2022/00611
	Singapore 510427.	Claim No :	-
		Policy No :	-

## PARTICULARS OF VEHICLE

Reg No :	FBQ9508E	Make/Model :	Yamaha Xmax	Year :	20/1/2020
Engine No :	H336E0067554	Chassis No :	MH3SH0847KK009313	Colour :	Dark Grey
Mileage :	45305 Km	Engine Cap :	292 cc	Seat Belt :	Nil
Aircon :	Nil	Radio/Cassette :	Nil	Rims :	Alloy

## VEHICLE CONDITION ( Static Test Only )

Brakes :	Serviceable	Handbrakes :	Serviceable	Steering :	Serviceable
General Body Works :	Good				

## TYRE CONDITIONS

Front O/S :	5	Rear O/S :	5	Make :	Pirelli
Front N/S :	\	Rear N/S :	\	Size :	120\70x15 \ 140\70x14

(Remaining Estimated Life Of Tyre in mm)

## GENERAL DESCRIPTION OF DAMAGES

The motor cycle sustained an on its n/s side body resulting both n/s and o/s side body parts damaged; n/s front brake lever, pillion bar, n/s pillion foot rest, front fork assy, body frame bent; headlamp, signal lamp, front fairing, cabon dashboard cover, view mirror, both mid lower fairing, both upper fairing, front cabon fender grazed/cracked. (see attached schedule for other damages)

Date of Accident :	11/11/2022	Date of Inspection :	16/11/22
Survey Held At :	Precise Auto Service	As Requested By :	Miss Arine
	1 Kaki Bukit Ave 6, #02-33/34	On :	16/11/2022
	Singapore 417883.		

## ADJUSTMENT AND RECOMMENDATION COST OF REPAIR

Repairer's Estimate :	\$9,046.67	
Revised Amount :	\$8,245.55	
Less Excess :	N.A	
Nett Total :	<b>\$7,000.00</b>	<b>(Lump Sum)</b>
Estimated Period Required For Repair :	<u>Six</u>	Days

Survey was conducted in accordance to your instructions. We ~~have~~ / have not authorised repairs.  
44 photos were taken at the time of inspection and attched.

Remarks : **The Survey was conducted strictly without prejudice.**

# TNECNIV SERVICES

## ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No : **FBQ9508E**

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST ( \$ )	OUR REVISED ( \$ )
	<b>TO SUPPLY</b>			
1 pc	n/s front brake lever	grazed/bent	118.50	118.50
1 pc	carbon air filter cover	grazed/cracked	436.60	436.60
1 pc	carbon battery cover	cracked	301.25	301.25
1 pc	carbon dashboard cover	grazed/cracked	1,292.50	1,292.50
1 pc	n/s carbon footrest fairing	grazed/cracked	373.10	373.10
1 pc	carbon front fender	grazed/cracked	222.30	222.30
1 pc	n/s carbon front lower fairing	cracked	276.55	276.55
1 pc	o/s carbon mid side fairing	cracked	185.10	185.10
1 pc	carbon under headlamp fairing/winglet	cracked	316.40	316.40
2 pc	front fork assy	bent	1,306.70	1,306.70
1 pc	hand o/s grip	bent/cut	52.75	52.75
2 pcs	front signal lamp	cracked	108.80	108.80
2 pc	front upper fairing (o/s and n/s)	cracked	470.20	470.20
1 pc	headlamp assy	cracked	1,253.60	1,253.60
2 pcs	L shape view mirror	bent/broken	108.90	108.90
2 pcs	side middle lower fairing (o/s and n/s)	cracked	273.60	273.60
1 pc	main stand	serviceable	181.10	-
1 pc	pillion bar	bent	203.55	203.55
1 pc	n/s pillion foot rest	bent	44.80	44.80
1 pc	n/s rear carbon protector	grazed	74.40	74.40
1 pc	n/s rear side fairing cover	cracked	246.10	246.10
1 pc	side stand	serviceable	78.50	-
1 pc	under belly cover	cracked	307.10	307.10
1 pc	o/s body "Yamaha" emblem	necessary	16.50	16.50
1 pc	o/s footrest rest plate	cracked	81.35	81.35
1 pc	front glove box compartment	o/s cracked	36.00	36.00
1 pc	front brake disc	serviceable	185.60	-
			8,551.85	8,106.65
	Less 10%		855.19	810.67
			7,696.67	7,295.99
	<b>Total Spare Parts</b>		<b>7,696.67</b>	<b>7,295.55</b>
	<b>LABOUR CHARGE</b>			
	To check, press and straighten body frame by Specialist.		350.00	200.00

## TNECNIV SERVICES

### ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No : **FBQ9508E**

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST ( \$ )	OUR REVISED ( \$ )
	To apply primer, to putty and paint accident affected areas.		500.00	400.00
	To remove damaged parts, straighten and knock bracket and replace recommended parts and re-alignment body parts after repairs.		500.00	350.00
	<b>Total Labour Charges</b>		<b>1,350.00</b>	<b>950.00</b>
	<b>GRAND TOTAL</b>		<b>9,046.67</b>	<b>8,245.55</b>
<b>Note:</b>	<p><b>The repairer had agreed to undertake the repairs on Lump Sum basis of \$7,000.00 nett to reinstate this motor cycle to its pre accident condition.</b></p> <p>( repairer discretion to repair parts, to replace with Second hand parts, or to replace with OEM or Genuine parts)</p>			
		End of Report		

## TNECNIV SERVICES

Summary

**Vincent Ng Seow Gim**

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 11-11-22

OUR REF : FBQ 9508E/T/22

### TAX INVOICE

**Muhammad Imran Bin Ramlan**

Blk 427 Pasir Ris Dr. 6

#07-45

Singapore 510427

Invoice No. : TP2301-010

DATE : 31-01-2023

FINAL BILL ON VEH. NO. : FBQ 9508E  
VEHICLE MODEL : YAMAHA XMAX 300

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

7,000.00

SUB-TOTAL	:	7,000.00
ADD GST 8%	:	560.00
TOTAL AMOUNT SGD	:	<u>7,560.00</u>

This is a computer generated document and requires no signature.