

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003369/UVY3Q2**Date:** 13/04/2023**REFERENCE**

| | | | |
|------------------------------|---|-----------------------------|--------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMHCSNW00012092202 |
| Claimant Vehicle No : | SMZ6640Y | Insured Vehicle No : | SMN5839L |
| Date of Loss: | 22/03/2023 | Nature of Claim: | TP |
| | | Claim No: | SNM23D202200/C02 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMZ6640Y | Engine No: | HR12372197C |
| Make & Model: | NISSAN KICKS, 1.2 L E-POWER (A) | Chassis No: | MNTFEAP15Z0002503 |
| Reg. Date: | 11/05/2021 (Man. Year: 2020) | Odometer: | 120016 km |
| Colour: | Blue | | |
| Engine Capacity: | 1198 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 205/55Z R17 | Rear Tyre Size: | 205/55Z R17 |
| Front Left Side: | RIVO 6 mm | Rear Left Side: | RIVO 6 mm |
| Front Right Side: | RIVO 6 mm | Rear Right Side: | RIVO 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 7,601.40 | 2,685.06 | 4,916.34 | 64.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,080.00 | 750.00 | 1,330.00 | 63.94 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,681.40 | 3,435.06 | 6,246.34 | 64.52 |
| Approved Total (Overridden) (S\$) | | 2,700.00 | | |
| (S\$) | 9,681.40 | 2,700.00 | 6,981.40 | 72.11 |
| + GST 8.00/8.00% (S\$) | 774.51 | 216.00 | 558.51 | 72.11 |
| Nett Amount (S\$) | 10,455.91 | 2,916.00 | 7,539.91 | 72.11 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 30/03/2023 | | |
| Date Inspected: | 30/03/2023 | Inspected At: | TLM Automobile Pte Ltd (HQ) 1 Defu Lane 6 Singapore 539365 |
| Estimated Period of Repair: | 3.0 days | | |

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 12 Apr 2023) |
| Parts: | M1-MPV | NISSAN KICKS 1.2 L E-POWER (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMZ6640Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------------------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deep Cut | 620.00 FN | *568.50 FN |
| 2 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 60.00 FN | *30.00 FN |
| 3 | 1 | | *FRONT BUMPER SIDE RETAINER | N/S Not Necessary / O/S Bent | 138.00 FN | *69.00 FN |
| 4 | 1 | | *FRONT BUMPER LH FOG GARNISH | Not Necessary | 142.00 FN | *- FN |
| 5 | 1 | | *FRONT BUMPER LH FOG LAMP | Not Necessary | 315.00 FN | *- FN |
| 6 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 590.00 FN | *- FN |
| 7 | 1 | | *FRONT BUMPER SPONGE TOP | Not Necessary | 195.00 FN | *- FN |
| 8 | 1 | | *HEADLAMPS | N/S Not Necessary / O/S Cracked | 4,100.00 FN | *1,699.90 FN |
| 9 | 2 | | *HEADLAMP LOWER CHROME GARNISH | Not Necessary | 590.00 FN | *- FN |
| 10 | 1 | | *FRONT FENDER | N/S Not Necessary / O/S Dented | 792.00 FN | *396.00 FN |
| 11 | 2 | | *FRONT FENDER INNER COWLING | Not Necessary | 364.00 FN | *- FN |
| 12 | 10 | | *FRONT FENDER INNER COWLING CLIPS | Not Necessary | 50.00 FN | *- FN |
| 13 | 1 | | *FRONT FENDER WHEEL ARCH GARNISH | N/S Not Necessary / O/S Grazed | 440.00 FN | *220.00 FN |
| 14 | 10 | | *FRONT FENDER WHEEL ARCH GARNISH CLIPS | Not Necessary | 50.00 FN | *- FN |

F=Franchise part. N=NettItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 8,446.00 | 2,983.40 |
| - Nett Item Discount on N Items 10.00/10.00% (S\$) | 844.60 | 298.34 |
| Total Parts (S\$) | 7,601.40 | 2,685.06 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 800.00 | 300.00 |
| 2 | TO PUTTY AND SPRAY PAINTING REAR OF THE AFFECTED PORTION | New | 1,000.00 | 400.00 |
| 3 | RUSTPROOF | New | 200.00 | 30.00 |
| 4 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 80.00 | 20.00 |
| Gross Labour Cost (\$\$) | | | 2,080.00 | 750.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >