

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III23001712/RQY3M4-1**Date:** 24/05/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005058\_03

**Claimant Vehicle No :** GBC4917P**Insured Vehicle No :** PA911B

Date of Loss: 07/02/2023

Nature of Claim: TP

Claim No: MFL2023D0001567

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBC4917P**

Make &amp; Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M)

Engine No: 1KD2229736

Reg. Date: 14/09/2012 (Man. Year: 2012)

Chassis No: JTFAT35Y80K202091

Colour: Blue

Odometer: 322505 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C

Rear Tyre Size: 155 R12C (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 5/5 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 5/5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,896.29	2,098.59	797.70	27.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,160.00	1,630.00	58.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,686.29</b>	<b>3,258.59</b>	<b>2,427.70</b>	<b>42.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,600.00</b>		
<b>(S\$)</b>	5,686.29	2,600.00	3,086.29	54.28
<b>+ GST 8.00/8.00% (S\$)</b>	454.90	208.00	246.90	54.28
<b>Nett Amount (S\$)</b>	<b>6,141.19</b>	<b>2,808.00</b>	<b>3,333.19</b>	<b>54.28</b>

**INSPECTION**

Date of Assignment: 29/03/2023

Date Inspected: 16/02/2023 Inspected At:

V-Tech Auto Service (HQ)

No.1 Soon Lee Street, #06-04 Pioneer Center  
Singapore 627605

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 May 2023)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4917P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Damaged	1,137.70 FL	*1,137.70 FL
2	1		*REAR TAILGATE LOCK HINGE	Damaged	110.50 FL	*110.50 FL
3	1		*REAR TAILGATE STOPPER BRACKET	Damaged	105.10 FL	*105.10 FL
4	1		*REAR TAILGATE DYNA EMBLEM	Necessary	34.10 FL	*34.10 FL
5	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	118.55 FL	*118.55 FL
6	1		*REAR TAILLAMP	Not Necessary	293.10 FL	*- FL
7	1		*REAR TAILLAMP PANEL	Not Necessary	105.50 FL	*- FL
8	1		*REAR SIDEGATE	Damaged	1,265.50 FL	*1,265.50 FL
9	1		*REAR SIDEGATE LOWER MEMBER	Not Necessary	625.00 FL	*- FL
10	1		*REAR TAILGATE 70 KM/H STICKER	Necessary	25.00 FS	*10.00 FS
11	1		*REAR TAILGATE 6 PAX STICKER	Necessary	25.00 FS	*10.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	3,845.05 2,791.45
					- List Item Discount on L Items 25.00/25.00% (\$\$)	948.76 692.86
					Total Parts (\$\$)	2,896.29 2,098.59

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS	New	40.00	20.00
2	TO REMOVE AND REFIT REAR TAILGATE ALUMINIUM	New	450.00	100.00
3	TO REMOVE AND REFIT REAR SIDEGATE ALUMINIUM	New	450.00	100.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	850.00	450.00
5	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	850.00	450.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	150.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,790.00</b>	<b>1,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >