

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003373/TNP3Q2**Date:** 30/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00003062306
Claimant Vehicle No :	SMC6291S	Insured Vehicle No :	SLL3979B
Date of Loss:	23/03/2023	Nature of Claim:	TP
		Claim No:	SNM23D202236/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6291S	Engine No:	B4204T182597165
Make & Model:	VOLVO XC40, 2.0 T5 MOMENTUM (A)	Chassis No:	YV1XZ16ACK2045416
Reg. Date:	13/07/2018 (Man. Year: 2018)	Odometer:	96321 km
Colour:	White		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,289.03	5,462.41	10,826.62	66.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	560.00	2,840.00	83.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,689.03	6,022.41	13,666.62	69.41
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	19,689.03	4,800.00	14,889.03	75.62
+ GST 8.00/8.00% (S\$)	1,575.12	384.00	1,191.12	75.62
Nett Amount (S\$)	21,264.15	5,184.00	16,080.15	75.62

INSPECTION

Date of Assignment:	31/03/2023	
Date Inspected:	11/04/2023	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2023)
Parts:	M1-SUV	VOLVO XC40 2.0 T5 MOMENTUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC6291S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,531.70 FL	*- FL
2	1		*SET BONNET INSULATOR CLIPS	Not Necessary	80.00 FL	*- FL
3	1		*FRONT BUMPER	Deformed	2,078.73 FL	*2,078.73 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FL	*40.00 FL
5	1		*SET FRONT BUMPER RIVETS	Necessary	70.00 FL	*30.00 FL
6	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	66.80 FL	*- FL
7	1		*FRONT BUMPER LOWER SPOILER	Cut	615.68 FL	*615.68 FL
8	1		*FRONT BUMPER LOWER CENTRE GARNISH	Not Necessary	780.19 FL	*- FL
9	1		*FRONT BUMPER RH SIDE GARNISH	Not Necessary	76.05 FL	*- FL
10	1		*FRONT BUMPER LH SIDE GARNISH	Not Necessary	76.05 FL	*- FL
11	1		*FRONT BUMPER LH PDC SENSOR	Not Necessary	215.50 FL	*- FL
12	1		*FRONT BUMPER CENTRE BRACKET	Not Necessary	85.68 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,399.77 FL	*- FL
14	1		*FRONT BUMPER RH SIDE BEAM	Not Necessary	159.03 FL	*- FL
15	1		*FRONT BUMPER LH SIDE BEAM	Not Necessary	159.03 FL	*- FL
16	1		*FRONT BUMPER CENTRE BEAM	Not Necessary	96.57 FL	*- FL
17	1		*FRONT BUMPER INNER SPONGE	Not Necessary	310.48 FL	*- FL
18	1		*RH HEADLAMP ASSY	Not Necessary	3,055.80 FL	*- FL
19	1		*LH HEADLAMP ASSY	Cracked	3,055.80 FL	*2,260.60 FL
20	1		*FRONT GRILLE	Cut	911.34 FL	*911.34 FL
21	1		*SET FRONT GRILLE CLIPS	Necessary	80.00 FL	*30.00 FL
22	1		*FRONT GRILLE EMBLEM	Necessary	103.00 FL	*103.00 FL
23	1		*AIRCON CONDENSER FRAME SUPPORT	Not Necessary	169.87 FL	*- FL
24	1		*AIRCON CONDENSER	Not Necessary	973.90 FL	*- FL
25	1		*RADIATOR ASSY	Not Necessary	690.18 FL	*- FL
26	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
27	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,081.15	6,069.35
- List Item Discount on L Items 10.00/10.00% (\$)	1,792.12	606.94
Total Parts (\$)	16,289.03	5,462.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	250.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	250.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	30.00
6	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR	New	280.00	0.00
7	REMOVE AND REPLACE RADIATOR ASSY AND HOSES TO ASSIST REPAIR	New	280.00	0.00
Gross Labour Cost (S\$)			3,400.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >