



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 6073G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE MIRROR	BROKEN	685.00	685.00
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	698.00	-
1	FRONT FENDER COWLING RH	SERVICEABLE	159.00	-
1	FRONT FENDER EMBLEM 'HYBRID'	NECESSARY	62.00	62.00
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,398.00	-
1	FRONT DOOR OUTER MOULDING RH	SERVICEABLE	159.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	687.00	-
	LESS 25% DISCOUNT		-962.00	-186.75
			2,886.00	560.25
<u>SPECIAL NETT ITEMS</u>				
1	SET FRT FENDER INNERSHIELD CLIP LH (SN)	NOT NECESSARY	50.00	-
1	FRT FENDER QUARTER GLASS SEALANT LH (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
			180.00	-
<u>LABOUR</u>				
	CHECK WIRING.		100.00	20.00
	R+R FRONT DOOR MECHANISM.	NOT NECESSARY	200.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	R+R FRT FENDER QUARTER GLASS LH.	NOT NECESSARY	120.00	-
	RESET TROUBLE CODE.	NOT NECESSARY	200.00	-
	KNOCK. INCLUSIVE OF THE REPAIR OF FRONT FENDER RH, FRONT DOOR RH AND FRONT BUMPER.		500.00	300.00
	SPRAY.		800.00	600.00
			2,040.00	920.00
GRAND TOTAL			5,106.00	1,480.25



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,150.00
---	--	--	----------

Report Ref No. CS/SMR23003381/Kwp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.