PROMINENT APPRAISER SERVICES PTE LTD

PAS

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0390922 Date of Report : 29/11/2022

To: Mr Lee Khai Ang
C/o. 25 Kaki Bukit Road 4
Synergy@KB #01-39
Singapore 417800

Date of Assignment
: 26/09/2022
: Mr Lee Khai Ang
Date of Accident
: 23/09/2022
: 23/09/2022
: Third Party Claim

Policy No. :-

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No.: SMQ5030LEngine Capacity (cc): 1595Make & Model: M/Benz A180Mileage (km): 120728km

Date of Registration : 19/06/2017 Chassis / Frame No. : WDD1760422J594726 Colour : Pearl Yellow Engine No. : 27091031261403

TYRE CONDITION

Front LH : 6 mm Front RH : 6 mm

Make : Michelin Make : Michelin

Rear LH : 6 mm Rear RH : 6 mm Make : Michelin Make : Michelin

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Nxpress Performance Pte Ltd

25, Kaki Bukit Road 4, Synergy@KB, #01-39, Singapore 417800

ASSESSMENT

Repairer's Estimate : \$ 37,859.72 Revised Amount : \$ 31,960.47

Less Excess : \$

Recommended Reserve : \$ 25,570.00 (Lump Sum)

Estimated Normal Period of Repairs : 24 Working Days

<u>Disclaimer:</u> The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SMQ5030L

Report No.: PAS/TP/0390922

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Nxpress Performance Pte Ltd, 25, Kaki Bukit Road 4, Synergy@KB, #01-39, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front bumper, front support panel, front chassis members, front fenders, radiator assy, a/c condenser, intercooler assy, headlamps, front grilles, front radar collision sensor, tailgate, rear bumper, rear end panel, rear floor panel, rear chassis members, rear fenders, rear exhaust muffler, taillamps, seat belts, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$31,960.47.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$25,570.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser

PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com Business Reg. 201404434D



Vehicle No: SMQ5030L

Report No.: PAS/TP/0390922

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition			Children Co.	pairer's imate (S\$)		Our sment (S\$)
			NAMES ASSESSMENT OF THE PARTY OF THE			Lst	mate (50)	110000	smelle (S\$)
1	1 pc	Bonnet	Dented/Repair			\$	1,618.00	\$	×
2	1 pc	Bonnet lock	Dented/Jammed			\$	139.00	\$	
3	2 pcs	Headlamp R/L	Cracked	\$	1,036.00	\$	2,072.00	nn §	
4		Frt grille assy (AMG)	Dented/Broken			\$	813.00	\$	
5	-	Frt bumper (AMG)	Dented			\$	1,452.00	\$	
6		Frt bumper no.plate garnish	Dented/Cracked			\$	83.00	\$	
7		Frt bumper parktronic sensor	Dented/Damaged	\$	220.00	\$	880.00	2pcs §	440.00 🗸
8		Frt bumper parktronic wireharness	Torn/Repair			\$	122.00	R §	- ×
9		Frt bumper center grille assy	Dented/Broken			\$	187.00	\$	2525000000000000
10	-	Frt bumper lip (AMG)	Dented/Broken			\$	341.00	S	341.00 🗸
11	-	Frt bumper reinforcement	Dented			\$	362.00	8	362.00 🗸
12	1 pc	Frt air duct	Broken			\$	87.00	\$	87.00 🗸
13		Frt intercooler	Dented			\$	989.00	5	989.00 🗸
14		Frt intercooler hose R/L	RH Cut	\$	86.00	\$	172.00	9	86.00 🗸
15		Frt intercooler air guide	Cracked			\$	58.00	9	58.00 🗸
16	-	A/c condenser	Dented/Bent			\$	1.187.00	9	
17	1 pc	Radiator assy	Dented/Cracked			\$	972.00	5	
18	1 pc	Radiator fan assy	Dented/Cracked			\$	562.00	8	
19	1 pc	Frt support panel	Dented/Distorted			\$	1,028.00	5	
20		Frt support bracket R/L	Cracked/Broken	\$	32.00	\$	64.00	5	4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
21	7.5	Frt support lower	Refit			\$	433.00	5	
22	1 pc	Frt radar collision pre. sensor	Dented/Damaged			\$	930.00	nn §	
23	l pc	Tailgate	Dented			\$	2,061.76	5	
24	1 pc	Tailgate emblem (Logo)	Necessary			\$	52.00	5	
25		Tailgate hinge R/L	Bent	\$	84.00	\$	168.00	nn S	
26		Tailgate hinge cover R/L	Cracked	\$	72.00	\$	144.00	nn §	
27	l pc	Tailgate inner trim garnish	Dented/Deformed			\$	179.00	nn s	
28	1 pc	Tailgate inner trim garnish lower	Dented/Deformed			S	91.00	nn s	
29	1 pc	Tailgate lock assy	Dented/Jammed			S	327.00	5	
30	1 pc	Tailgate weatherstrip	Torn/Necessary			\$	246.00	9	
31 1		Taillamp R/L (RH)	Cracked/Broken	\$	682.00	\$	1,364.00		
32	-	Taillamp panel R/L	Dented/Repair	\$	183.00	\$	366.00	9	
33		Rr bumper (AMG)	Dented			\$	1,448.00	9	1,448.00 🗸
34		Rr bumper parktronic sensor	Dented/Damaged	\$	220.00	\$	1,320.00	4pcs S	the state of the s
35		Rr parktronic sensor wireharness	Torn/Damaged			\$	192.00		
36	-	Rr bumper tow cover	Broken			S	28.00		
37		Rr bumper diffuser assy (AMG)	Broken/Dislodged/M	issing		\$	286.00		
38		Rr bumper side trim R/L	LH Cracked	\$	64.00	\$	128.00		
39	100 - 100 -	Rr bumper center guide	Dented/Cracked	4	00	\$	226.00		
40		Rr bumper side guide R/L	Cracked/Necessary	\$	63.00	\$	126.00		
41		Rr bumper side rail R/L	Cracked/Necessary	\$	38.00	\$	76.00		
42		Rr bumper reinforcement	Dented	142	20.00	\$	544.00		
43		Rr end panel assy	Dented			\$	895.00		
44		Rr end panel inner garnish	Dented/Cracked			\$	106.00		106.00 V
45		Rr fender inner trim R/L	Serviceable	\$	229.00	\$	458.00		
46	_	Rr compartment cover lid	Serviceable	96	222.00	\$	705.00		
47		Rr floor panel trim	Serviceable			\$	183.00		
48		Rr floor panel	Dented/Buckled			\$	973.00		
10	. pc	14 Hoor paner	Denied Duckied			_	27,243.76		\$ 22,328.76

PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com Business Reg. 201404434D

Vehicl	e No : S	SMQ5030L					Report No		and the state of t
S/No.	Qty	Parts Descriptions	Condition			Charles Landers	pairer's timate (S\$)	Our Assessment (S\$)	
						\$	27,243.76	\$	22,328.76
49	l pc	Rr floor panel insulator	Affected/Necessary			\$	133.00	\$	133.00 🗸
50	1 pc	Rr exhaust muffler	Dented			\$	1,142.00	\$	1,142.00 🗸
51	2 pcs	Rr exhaust tip (AMG) R/L	Broken/Dislodged/ Missing	\$	148.00	\$	296.00	\$	296.00 🗸
52	1 pc	Rr exhaust heat insulator	Dented			\$	148.00	\$	148.00 🗸
53	2 pcs	Frt seat belt R/L	Jammed/Pretensioner Activated	\$	682.00	\$	1,364.00	\$	1,364.00 🗸
54	2 pcs	Rr seat belt R/L	Jammed/Pretensioner Activated	\$	397.00	\$	794.00	\$	794.00 ✓
55	1 pc	Bonnet	Dented/Repair (Refer labour no. 7 & 8						
56	2 pcs	Frt fender R/L	Dented/Repair	(Refer labour no. 7 & 8)				no. 7 & 8)	
57	2 pcs	Frt chassis member R/L	Dented/Repair	(Refer labour no. 7, 8 & 17)				7, 8 & 17)	
58	2 pcs	Rr taillamp panel R/L	Dented/Repair	(Refer labour no. 12, 13, 18 & 19)				, 18 & 19)	
59	2 pcs	Rr fender R/L	Dented/Repair			(Refer labour no. 12, 13, 18 & 19)			
60	2 pcs	Rr chassis member R/L	(Refer labour no. 12, 13, 17, 18				', 18 & 19)		
			20,966.76			\$	31,120.76	\$	26,205.76
			-10%	Less I	Discount: 5		1,556.04		1,310.29
			18,870.08 List l	Parts S	ub-Total:	\$	29,564.72		24,895.47
61	1 set	Frt no.plate (3D, w/bracket)	Dented/Broken		S/N	\$	120.00	\$	120.00 10
62		Radiator coolant	Necessary		S/N	\$	50.00	\$	50.00 40
63	1 pc	Rr no.plate bracket	Broken		S/N	\$	15.00	\$	15.00 🗸
64	1 pc	Rr windscreen sealant	Necessary		S/N	\$	50.00	\$	40.00 🗸
65	1 pc	Rr end panel sealant	Necessary		S/N	\$	50.00	\$	40.00 🗸
66	1 pc	Rr floor panel sealant	Necessary		S/N	\$	50.00	\$	nn 40.00 X
			235	Par	ts Total :	8	29,899.72	\$	25,200.47

S/No.	Labour Descriptions		Repairer's Estimate (S\$)		our nent (S\$)
1	Towing.	\$	120.00	s	120.00 80
2	To remove and reinstall front electrical wiring system for necessary repairs. To check electrical system, repair wire harness and focus headlamp.	\$	60.00	\$	50.00 ✓
3	To remove, replace and reinstall a/c condenser & a/c pipings. (Include vacuum & recharge a/c gas)	\$	120.00	\$	120.00 🗸
4	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$	100.00	\$	80.00 🗸
5	To remove, replace and reinstall intercooler assy & pipings. (Include pressure test air intake system)	\$	100.00	\$	60.00 🗸
6	To remove, replace and/or transfer front parktronic sensors to new bumper.	\$	20.00	\$	20.00 🗸
7	To straighten, repair, realign on front affected area and replace damaged parts.	\$	1,200.00	\$	880.00 600
8	To spray painting (Pearl Yellow), blending on front affected and adjacent area.	\$	1,500.00	\$	1,200.00 500

PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191. Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicl	Vehicle No : SMQ5030L				Report No. : PAS/TP/0390922				
S/No.	Labour Descriptions		A TOTAL STREET, STREET	oairer's imate (S\$)		our nent (S\$)			
	To remove and reinstall rear electrical wiring system for check rear electrical wiring system.	or necessary repairs.	\$	60.00	\$	50.00 ✓			
10	To transfer rear windscreen to new tailgate.		\$	120.00	\$	120.00 🗸			
	To transfer tailgate component parts to new tailgate. (Include transfer tailgate spoiler & supply sealant/adhe	esive tape)	\$	150.00	S	120.00 80			
12	To remove and reinstall rear interior trims, garnishes, s	seats, etc. for necessary repairs.	\$	100.00	S	80.00 🗸			
13	To remove and reinstall rear undercarriage for necessa	ry repairs.	\$	200.00	\$	200.00 🗙			
14	To conduct rear wheel alignment.		\$	60.00	\$	60.00 🗸			
	To remove and reinstall exhaust muffler for necessary repairs. To straighten, repair, realign center exhaust pipe and replace exhaust muffler.			100.00	\$	80.00 🗸			
16	To remove, replace and/or transfer rear parktronic sensors to new bumper.		\$	20.00	\$	20.00 🗸			
17	To conduct chassis alignments.		\$	300.00	\$	300.00 ★			
18	To straighten, repair, realign on rear affected area and	replace damaged parts.	\$	1,500.00	\$	1,320.001200			
19	To spray painting (Pearl Yellow), blending on rear affe	ected and adjacent area.	\$	1,500.00	\$	1,300.001000			
20	To spray anti-rust coating on new and affected panels.		\$	30.00	\$	30.00 🗸			
21	To remove, replace and reinstall front & rear seat belts	s.	\$	200.00	\$	200.00 150			
23	To inspection, diagnose, reset and perform coding pro 2.1) Front radar collision control system. 2.2) Parktronic control module.	gramming on:-							
	2.3) Airbag/Seat belt control module. 2.4) Engine Control Unit.	4380	\$	400.00	\$	350.00			
	Control Contro	Labour Total:	\$	7,960.00	\$	6,760.00			
		Total (Parts & Labour):	\$	37,859.72		31,960.47			
For 1	Lump Sum Repairs	14 days		485.08 - 18,788.06					
The final adjusted Lump Sum contract amount is \$ 25,570.00		25,570.00	L/S	= 18,800.00)				

Under normal circumstances, the repairs should be completed within a reasonable period

24 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

250 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.