



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 1638B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	1,660.20	1,557.00
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
1	FRONT GRILLE	CRACKED	586.25	586.25
1	FRONT EMBLEM	NECESSARY	135.50	135.50
	LESS 5% DISCOUNT		-121.05	-
	LESS 10% DISCOUNT		-	-231.77
			2,299.90	2,085.98
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER PROXIMITY SENSOR (SN)	CUT	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	DISMANTLE AND CHANGE FRONT BUMPER PROXIMITY SENSOR, FRONT BUMPER, FRONT GRILLE, KNOCKING FRONT BONNET AND REALIGN FRONT PORTION.		800.00	400.00
	TO DO WIRE CHECKING.		50.00	20.00
	TO SPRAY FRONT BUMPER AND FRONT BONNET.		600.00	440.00
			1,450.00	860.00
	GRAND TOTAL		3,949.90	3,145.98
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00

Report Ref No. CS/UOI23003399/Kvp3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.