

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 7588P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR LH	DENTED	2,688.00	1,127.00
1	FRONT DOOR MOULDING LH	NOT NECESSARY	286.00	-
1	FRONT DOOR LOCK LH	JAMMED	625.00	262.00
1	FRONT DOOR INNER TRIM LH	CRACKED	1,020.00	611.00
1	REAR DOOR LH	DENTED	2,158.00	954.00
1	REAR DOOR HINGE UPPER LH	NOT NECESSARY	168.00	-
1	REAR DOOR HINGE LOWER LH	BENT	168.00	120.00
1	REAR DOOR CHECKER LH	NOT NECESSARY	268.00	-
1	REAR DOOR MOULDING LH	NOT NECESSARY	308.00	-
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	308.00	-
1	REAR DOOR LOCK	NOT NECESSARY	552.00	-
1	REAR DOOR INNER TRIM LH	NOT NECESSARY	1,043.00	-
1	REAR DOOR REGULATOR WITH MOTOR LH	NOT NECESSARY	478.00	-
1	SIDE SKIRT LH	NOT NECESSARY	579.00	-
	LESS 20% DISCOUNT		-2,129.80	-614.80
			8,519.20	2,459.20
	SPECIAL NETT ITEMS			
1	FRONT DOOR INNER TRIM CLIPS (SN)	NECESSARY	100.00	20.00
1	REAR DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	SIDE SKIRT CLIPS (SN)	NOT NECESSARY	100.00	-
			300.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,400.00	400.00
	TO CHECK WIRING.		200.00	30.00
	TO SPRAY PAINTING.		1,400.00	660.00
			3,000.00	1,090.00
	GRAND TOTAL		11,819.20	3,569.20



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,850.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS3/INC22009015/Dvp3m4-1



Automotive Assessor / Investigator