

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD	Ref	:	CS3/LPC23003407/Wqp3e2
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Dat	e:	13/04/2023
			Cod	de:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 86H	Veh. Inspected		SLX 315Z
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/23/23/VC05/027200	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		31/03/2023
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI ATTRAGE	c.c		1193
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	MMBSTA13AJH000890	Colour		RED
	Odometer	228232 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/55 R15	HABILEAD		6 mm
	L/H Front Tyre	195/55 R15	HABILEAD		6 mm
	R/H Rear Tyre	195/55 R15	HABILEAD		6 mm
	L/H Rear Tyre	195/55 R15	HABILEAD		6 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	31/03/2023	Inspect Date / Time	е	31/03/2023 ( 04:50 PM )
	Survey held at	BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #05-04			
	Repairer	MERLIN MOTOR & ENGINEERING WORKS			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC23003407/Wqp3e2

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser