



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 4950H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	REPLACED	230.00	230.00
1	FRONT O/S FORK ASSY	REPAIRED SEE LABOUR	1,278.00	-
1	FRONT N/S FORK ASSY	REPAIRED SEE LABOUR	1,278.00	-
1	FORK UNDER BRACKET	SERVICEABLE	650.00	-
1	O/S SIDE MIRROR	REPLACED	80.00	80.00
1	HANDLE-BAR	REPLACED	255.00	255.00
1	SET HANDLE-BAR BALANCER	REPLACED	45.00	45.00
1	BRAKE LEVER	SERVICEABLE	80.00	-
1	FUEL TANK CENTRE COVER	REPAIRED SEE LABOUR	255.00	-
1	O/S SIDE BOARD	REPAIRED SEE LABOUR	85.00	-
1	FRONT O/S FOOTREST	REPLACED	45.00	45.00
1	FRONT O/S FOOTREST BRACKET	REPLACED	90.00	90.00
1	BRAKE PEDAL	REPLACED	75.00	75.00
2	REAR FOOTRESTS	N/S SERVICEABLE / O/S REPLACED	110.00	55.00
2	REAR FOOTREST BRACKETS	N/S SERVICEABLE / O/S REPLACED	210.00	105.00
2	REAR TAILBOARDS	REPAIRED SEE LABOUR	570.00	-
2	REAR SIGNALS	REPLACED	150.00	150.00
1	EXHAUST ASSY	REPLACED	855.00	855.00
1	EXHAUST END CAP	REPLACED	48.00	48.00
1	EXHAUST PROTECTOR	REPLACED	65.00	65.00
1	REAR FENDER	REPLACED	85.00	85.00
1	REAR FENDER INNER BRACKET	REPLACED	175.00	175.00
1	SWING ARM	REPLACED	1,050.00	1,050.00
1	CHAIN COVER	REPLACED	55.00	55.00
1	REAR TAILLAMP	REPLACED	195.00	195.00
1	REAR SPORT RIM	REPLACED	850.00	850.00

Report Ref No. CS/LAW23003422/Uvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RIM SHAFT	REPLACED	65.00	65.00
1	REAR BRAKE DISC	REPLACED	185.00	185.00
	LESS 10% DISCOUNT		-911.40	-475.80
			8,202.60	4,282.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	REPLACED	18.00	18.00
2	FORK OILS (SN)	NECESSARY	40.00	40.00
2	FORK OIL SEALS (SN)	NECESSARY	70.00	70.00
1	SET STEERING CONE (SN)	NECESSARY	95.00	95.00
1	REAR TYRE (DEPRACIATION) (SN)	REPLACED	350.00	150.00
1	REAR CAMERA (SN)	REPLACED	450.00	280.00
			1,023.00	653.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.	REFER LOD	50.00	-
	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT O/S FORK ASSY, FRONT N/S FORK ASSY, FUEL TANK CENTRE COVER, O/S SIDE BOARD AND REAR TAILBOARDS. }		450.00	380.00
	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP. }		80.00	-
			580.00	380.00
GRAND TOTAL			9,805.60	5,315.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS/LAW23003422/Uvy3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.