



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 6997Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH OUTSIDE MIRROR HEATED WITH MEMORY (SN)	MISSING	859.90	859.90
1	LH MIRROR GLASS HEATED WIDE ANGLE (SN)	CRACKED	435.90	435.90
1	LH OUTSIDE MIRROR COVER CAP PRIMED (SN)	MISSING	133.90	133.90
1	SUNDRIES (SN) (ADDITIONAL)	NECESSARY	40.00	40.00
			1,469.70	1,469.70
LABOUR				
	TO REMOVE AND REPLACE LEFT WING MIRROR.		450.00	425.00
	TO CHECK ELECTRICAL WIRING.		177.00	168.00
	TO RESPRAY LEFT WING MIRROR CAP.		74.00	70.00
			701.00	663.00
GRAND TOTAL			2,170.70	2,132.70
RECOMMENDED COST OF REPAIRS				2,132.70

Report Ref No. CS/FCI23003439/Rqy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.