



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003439/Rqy3m4 Date: 28/06/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YP 1711U	Veh. Inspected	SND 6997Y
Policy No.		Coverage (\$)	0.00
Claim No.	D23001128MFCV	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	31/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	B.M.W 218I GC MSPT HL	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	WBA12AK0907K41268	Colour	BLACK
Odometer	13149 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/40R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS			
<b>5. General Information</b>			
Accident Date	31/03/2023	Inspection Date	03/04/2023
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	