

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA23003443/KWY3Q2**Date:** 28/04/2023**REFERENCE**

Insured/Claimant:	HENG SIEW HOON	Policy No:	MP307949	
Date of Loss:	30/03/2023	Nature of Claim:	OD	Claim No: MPC04076

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBM7333B	Engine No:	HR16913051C
Make & Model:	NISSAN SYLPHY, 1.6 CVT (A)	Chassis No:	MNTBBAB17Z0030181
Reg. Date:	19/08/2017 (Man. Year: 2017)	Odometer:	86730 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,004.70	3,621.45	383.25	9.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,870.00	430.00	18.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,304.70	5,491.45	813.25	12.90
Approved Total (Overridden) (\$\$)		4,350.00		
- Excess (\$\$)	0.00	250.00	-250.00	
(\$\$)	6,304.70	4,100.00	2,204.70	34.97
+ GST 8.00/8.00% (\$\$)	504.38	328.00	176.38	34.97
Nett Amount (\$\$)	6,809.08	4,428.00	2,381.08	34.97

INSPECTION

Date of Assignment:	03/04/2023	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	04/04/2023	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBM7333B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR RH DOOR (WCP)	Bent	600.00 F	*600.00 F
2	1		*1 PC REAR RH DOOR LOWER MOULDING (WCP)	Necessary	110.00 F	*110.00 F
3	1		*1 PC REAR RH DOOR FRAME STICKER (WCP)	Necessary	60.00 F	*60.00 F
4	1		*1 PC REAR RH DOOR TOP HINGE (WCP)	Repair	45.00 F	*- F
5	1		*1 PC REAR RH DOOR INNER RUBBER (WCP)	Serviceable	70.00 F	*- F
6	1		*1 PC FRT RH DOOR (WCP)	Bent	630.00 F	*630.00 F
7	1		*1 PC FRT RH DOOR LOWER MOULDING (WCP)	Necessary	110.00 F	*110.00 F
8	1		*1 PC FRT RH DOOR FRAME STICKER (WCP)	Necessary	42.00 F	*42.00 F
9	1		*1 PC FRT RH DOOR TOP HINGE (WCP)	Repair	55.00 F	*- F
10	1		*1 PC FRT RH DOOR OUTER CHROME HANDLE (WCP)	Serviceable	120.00 F	*- F
11	1		*1 PC FRT RH DOOR INNER RUBBER (WCP)	Serviceable	75.00 F	*- F
12	1		*1 PC FRT RH DOOR INNER LOCK (WCP)	Dented	130.00 F	*130.00 F
13	1		*1 PC FRT RH DOOR GLASS OUTER MOULDING (WCP)	Buckled	110.00 F	*110.00 F
14	1		*1 PC FRT RH DOOR SIDE MIRROR ASSY (WCP)	Broken	230.00 F	*230.00 F
15	1		*1 PC FRT RH FENDER (WCP)	Bent	450.00 F	*450.00 F
16	1		*1 PC FRT RH FENDER LAMP (WCP)	Broken	35.00 F	*35.00 F
17	1		*1 PC FRT BUMEPR (WCP)	Buckled	350.00 F	*350.00 F
18	1		*1 PC FRT BUMPER SIDE RETAINER RH (WCP)	Distorted	30.00 F	*30.00 F
19	1		*6 PCS FRT BUMPER CLIP @2/PCE (WCP)	Necessary	12.00 F	*12.00 F
20	1		*1 PC RH HEADLAMP (WCP)	Cut	550.00 F	*550.00 F

F=Franchise part.

Sub Total (S\$)		3,814.00	3,449.00
+ Margin on L,N Items 5.00/5.00% (S\$)		190.70	172.45
Total Parts (S\$)		4,004.70	3,621.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) TO REMOVE AND REFIX FRT BUMPER ASSY, RH HEADLAMP, FRT RH FENDER, FRT & REAR RH DOORS, TRNASFER LOCK ASSY, INNER TRIM BOARD; KNOCK AND REPAIR FRT RH WINDSCREEN PILLAR, RH CENTRE PILLAR AND RE-ALIGN TO SAME	New	1,000.00	750.00
2	2) TO REMOVE AND REFIX FRT & REAR RH DOOR GLASS	New	120.00	120.00
3	3) TO PUTTY AND RESPRAY ON FRT & RER RH DOORS, PILLARS, FRT RH FENER, FRT BUMPER	New	1,100.00	1,000.00
4	4) TO RESET LOCK SYSTEM	New	80.00	0.00
Gross Labour Cost (\$\$)			2,300.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >