

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123003453/AQY3Q2**Date:** 11/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : YN3845P **Insured Vehicle No :** YQ4768G

Date of Loss: 30/03/2023 Nature of Claim: TP Claim No: CDMCG23000784

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN3845P**

Make & Model: MITSUBISHI FB511B0JRDEB, 2.8 D (M) Engine No: 6M60175479

Reg. Date: 09/05/2013 (Man. Year: 2013) Chassis No: FM65FMA10018

Colour: Blue Odometer: 87007 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,250.00	2,280.00	19,970.00	89.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,220.00	1,280.00	51.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,750.00	3,500.00	21,250.00	85.86
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	24,750.00	2,800.00	21,950.00	88.69

INSPECTION

Date of Assignment: 03/04/2023

Date Inspected: 05/04/2023 Inspected At: 1 KAKI BUKIT AVENUE 6
#02-11 AUTOBAY
SINGAPORE 417883
Repairer: Automobile Hub Enterprise

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jul 2023)	
Parts:	N/A	MITSUBISHI FB511B0JRDEB 2.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN3845P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented	2,500.00 FS	*1,300.00 FS
2	2		*REAR HYDRAULIC PUMP (OUTER)	Not Necessary	6,000.00 FS	*- FS
3	2		*REAR HYDRAULIC PUMP (INNER)	Not Necessary	4,800.00 FS	*- FS
4	1		*TAILGATE (ALUMINIUM)	Repair	7,500.00 FS	*- FS
5	1		*TAILGATE LOWER BEAM	Dented	1,200.00 FS	*900.00 FS
6	1		*TAILGATE LOWER BEAM STICKER	Necessary	250.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					22,250.00	2,280.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	800.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	800.00	400.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	40.00
5	TO REMOVE TAILGATE	New	300.00	250.00
6	TO REMOVE HYDRALIC PUMPS	New	400.00	0.00
Gross Labour Cost (S\$)			2,500.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >