

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23003465/HWP3E2**Date:** 21/06/2023REFERENCE

Insured/Claimant:	SIVANANDAN INBASAKARAM	Policy No:	SP2004246356-01
Date of Loss:	31/03/2023	Nature of Claim:	OD
		Claim No:	202332006757

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLF9294K</b>	Engine No:	P520368382
Make & Model:	MAZDA 3, 1.5 SEDAN (A)	Chassis No:	JM6BM42A8G0342791
Reg. Date:	16/09/2016 (Man. Year: 2016)	Odometer:	92338 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$45,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bluearth 5 mm	Rear Left Side:	Bluearth 5 mm
Front Right Side:	Bluearth 5 mm	Rear Right Side:	Bluearth 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,788.00	5,681.00	107.00	1.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,100.00	800.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,688.00</b>	<b>6,781.00</b>	<b>907.00</b>	<b>11.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,750.00</b>		
<b>- Excess (S\$)</b>	0.00	600.00	-600.00	
<b>(S\$)</b>	7,688.00	4,150.00	3,538.00	46.02
<b>+ GST 8.00/8.00% (S\$)</b>	615.04	332.00	283.04	46.02
<b>Nett Amount (S\$)</b>	<b>8,303.04</b>	<b>4,482.00</b>	<b>3,821.04</b>	<b>46.02</b>

INSPECTION

Date of Assignment:	03/04/2023	Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	03/04/2023	Inspected At:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore 528840
Estimated Period of Repair:	4.0 days		

**Adjuster:** Edward**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2023)
<b>Parts:</b>	143	MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF9294K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BUMPER</b> (WCP)	Cracked	680.00 F	*680.00 F
2	1		<b>*O/S FRONT BUMPER SIDE RETAINER</b> (WCP)	Necessary	25.00 F	*25.00 F
3	10		<b>*FRONT BUMPER CLIPS</b>	Necessary	30.00 FS	*30.00 FS
4	10		<b>*FRONT BUMPER RIVETS</b>	Not Necessary	30.00 FS	*- FS
5	1		<b>*O/S FRONT FENDER</b> (WCP)	Buckled	350.00 F	*350.00 F
6	1		<b>*O/S FRONT FENDER INNER SHIELD</b> (WCP)	Torn	85.00 F	*85.00 F
7	10		<b>*O/S FRONT FENDER INNER SHIELD CLIPS</b>	Necessary	30.00 FS	*30.00 FS
8	1		<b>*O/S HEADLAMP</b> (WCP)	Cracked	1,600.00 F	*1,600.00 F
9	1		<b>*O/S SIDE MIRROR COVER</b> (WCP)	Missing	70.00 F	*70.00 F
10	1		<b>*O/S SIDE MIRROR LAMP</b> (WCP)	Not Necessary	70.00 F	*- F
11	1		<b>*O/S SIDE MIRROR</b> (WCP)	Broken	280.00 F	*280.00 F
12	1		<b>*O/S FRONT RIM</b> (WCP)	Cut	850.00 F	*850.00 F
13	1		<b>*O/S FRONT WHEEL BEARING</b> (WCP)	Distorted	300.00 F	*300.00 F
14	1		<b>*O/S FRONT KNUCKLE ARM</b> (WCP)	Bent	250.00 F	*250.00 F
15	1		<b>*O/S FRONT LOWER ARM</b> (WCP)	Bent	300.00 F	*300.00 F
16	1		<b>*O/S FRONT SHOCK ABSORBER</b> (WCP)	Bent	240.00 F	*240.00 F
17	1		<b>*O/S FRONT SHOCK ABSORBER TOP MOUNTING</b> (WCP)	Necessary	80.00 F	*80.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>5,270.00</b>	<b>5,170.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	518.00	511.00
<b>Total Parts (\$\$)</b>	<b>5,788.00</b>	<b>5,681.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT	New	120.00	60.00
2	TO TRANSFER TYRE TO NEW RIM BALANCE	New	80.00	30.00
3	TO CHECK LIGHT AND WIRING	New	50.00	30.00
4	TO REMOVE/REPLACE FRONT UNDERCARRIAGE PARTS	New	250.00	180.00
5	TO REMOVE NECESSARY PARTS TO REPAIR INNER PANEL, REPLACE ACCIDENT DAMAGED PARTS AND ALIGN THE SAME	New	600.00	400.00
6	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	New	800.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>1,900.00</b>	<b>1,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >