

ASS. REC. BY:

REF:

A15/23003468/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STQ 78294

Yr Regn:

05, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

c.c

1591

Colour

n. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

286333

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH DU 41 BR 90 757871

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

31/3/23

D.O.I.

13/4/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/4 11pm @ 27006 Carhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**WONG WEI SIONG DENNIS**

57 SUNRISE AVENUE

#03-01 SUNRISE GARDENS

Singapore 806748

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	31/03/2023
Vehicle Reg. No.:	SJQ7829Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	WONG WEI SIONG DENNIS		
Make/Model:	HYUNDAI AVANTE, 1.6 HD (A)	Vehicle Reg. Date:	27/05/2009
Vehicle Colour:	Silver	Chassis No:	KMH DU41BR9U757871
Engine No:	G4FC9U652994		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 <i>5 days</i>		
Description of Accident/Loss	COLLISION - HEAD TO REAR (TP HIT INSURED)		
Present Location:	DING AUTO PTE LTD (HQ)		

*NOT WITHIN
LI Rep &
Mercury After Paim*

COST OF CLAIMS

	Amount
Parts	3,429.80
Miscellaneous Items	50.00
Labour	3,030.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,509.80
+ GST 8.00% (S\$)	520.78
Nett Amount (S\$)	7,030.58

This claim is handled by: YAP WEI LIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts: 143 HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BOOTLID	0.00	0.00	R ₁ *500.00 F	✓
2	1		*REAR BUMPER	0.00	0.00	R ₁ *340.00 F	✓
3	1		*REAR BUMPER REINFORCEMENT	R ₁ 0.00	0.00	*216.00 F	✓
4	1		*REAR INNER TAIL LAMP LHS	0.00	0.00	CM *130.00 F	✓
5	1		*REAR INNER TAIL LAMP RHS	0.00	0.00	P ₁ *130.00 F	✓
6	1		*REAR OUTER TAIL LAMP LHS	0.00	0.00	CM *174.00 F	✓
7	1		*REAR OUTER TAIL LAMP RHS	0.00	0.00	P ₁ *174.00 F	✓
	1		*REAR END PANEL	0.00	0.00	R ₁ *198.00 F	✓
9	1		*REAR SPARE TYRE PANEL	0.00	0.00	R ₁ *342.00 F	X
10	1		*REAR BOOTLID SPARE TYRES BOARD	P ₁ 0.00	0.00	*108.00 F	X
11	1		*REAR BOOTLID LOGO	0.00	0.00	R ₁ *21.00 F	✓
12	1		*REAR BUMPER REVERSE SENSOR LHS	R ₁ 0.00	0.00	*308.00 F	2 min
13	1		*REAR BUMPER REVERSE SENSOR RHS	P ₁ 0.00	0.00	*308.00 F	X
14	1		*BOOTLID INNER TRIM	0.00	0.00	CM *108.00 F	✓
15	1		*REAR BOOTLID WEATHER STRIP	0.00	0.00	DIY *61.00 F	✓
						Sub Total (S\$)	3,118.00
						+ Margin on L,N Items 10.00% (S\$)	311.80
						Total Parts (S\$)	3,429.80

F=Franchise part.

Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

11 Sep @ 2700h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR CARPLATE WITH FRAME	50.00 <i>0d 455n</i>
Sub Total (S\$)			50.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEAT, REPAIR & STRAIGHTEN - ACCIDENT AREAS	New	1,500.00 <i>800</i>
2	SPRAY PAINTING FOR REAR ACCIDENT AREAS	New	1,200.00 <i>800</i>
3	CHECK WIRING	New	80.00 <i>200</i>
4	REMOVE & REFIT - REAR BOOTLID COMPONENTS	New	120.00 <i>500</i>
5	REMOVE, REFIT & TEST - REVERSE SENSOR	New	50.00 <i>✓</i>
6	RUST PROOFING	New	80.00 <i>600</i>
Gross Labour Cost (S\$)			3,030.00

Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >