

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

WONG WEI SIONG DENNIS

57 SUNRISE AVENUE

#03-01 SUNRISE GARDENS

Singapore 806748

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	31/03/2023
Vehicle Reg. No.:	SJQ7829Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (Insured):	WONG WEI SIONG DENNIS		
Make/Model:	HYUNDAI AVANTE, 1.6 HD (A)	Vehicle Reg. Date:	27/05/2009
Vehicle Colour:	Silver		
Engine No:	G4FC9U652994	Chassis No:	KMH DU41BR9U757871
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 5 days		
Description of Accident/Loss	COLLISION - HEAD TO REAR (TP HIT INSURED)		
Present Location:	DING AUTO PTE LTD (HQ)		

NOT Authorized
L/R &
Mercury After Pain

COST OF CLAIMS

Amount

Parts	3,429.80
Miscellaneous Items	50.00
Labour	3,030.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,509.80
+ GST 8.00% (S\$)	520.78
Nett Amount (S\$)	7,030.58

This claim is handled by: YAP WEI LIN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2023)

Parts: 143 HYUNDAI AVANTE 1.6 HD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BOOTLID	0.00	0.00	<i>RM</i> *500.00 F	✓
2	1		*REAR BUMPER	0.00	0.00	<i>RM</i> *340.00 F	✓
3	1		*REAR BUMPER REINFORCEMENT	0.00	0.00	*216.00 F	✓
4	1		*REAR INNER TAIL LAMP LHS	0.00	0.00	<i>CM</i> *130.00 F	✓
5	1		*REAR INNER TAIL LAMP RHS	0.00	0.00	<i>RM</i> *130.00 F	✓
6	1		*REAR OUTER TAIL LAMP LHS	0.00	0.00	<i>CM</i> *174.00 F	✓
7	1		*REAR OUTER TAIL LAMP RHS	0.00	0.00	<i>RM</i> *174.00 F	✓
8	1		*REAR END PANEL	0.00	0.00	<i>RM</i> *198.00 F	✓
9	1		*REAR SPARE TYRE PANEL	0.00	0.00	<i>RM</i> *342.00 F	X
10	1		*REAR BOOTLID SPARE TYRES BOARD	0.00	0.00	*108.00 F	✓
11	1		*REAR BOOTLID LOGO	0.00	0.00	<i>RM</i> *21.00 F	✓
12	1		*REAR BUMPER REVERSE SENSOR LHS	<i>RM</i> 0.00	0.00	*308.00 F	20012
13	1		*REAR BUMPER REVERSE SENSOR RHS	0.00	0.00	*308.00 F	X
14	1		*BOOTLID INNER TRIM	0.00	0.00	<i>CM</i> *108.00 F	✓
15	1		*REAR BOOTLID WEATHER STRIP	0.00	0.00	<i>RM</i> *61.00 F	✓

F=Franchise part.

Sub Total (S\$)	3,118.00
+ Margin on L,N Items 10.00% (S\$)	311.80
Total Parts (S\$)	3,429.80

Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 REAR CARPLATE WITH FRAME

04 50.00 4552

Sub Total (S\$)

50.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEAT, REPAIR & STRAIGHTEN - ACCIDENT AREAS

New

1,500.00 804

2 SPRAY PAINTING FOR REAR ACCIDENT AREAS

New

1,200.00 804

3 CHECK WIRING

New

80.00 201

4 REMOVE & REFIT - REAR BOOTLID COMPONENTS

New

120.00 501

5 REMOVE, REFIT & TEST - REVERSE SENSOR

New

50.00 ✓

6 RUST PROOFING

New

80.00 601

Gross Labour Cost (S\$)

3,030.00

Ding Auto Pte Ltd/SJQ7829Y/03/04/2023 09:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >