



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7995H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	55.80	-
1	FRONT BUMPER	DEFORMED	481.10	481.10
1	FRONT BUMPER CENTRE UPPER MOULDING	TO REPAIR SEE LABOUR	368.50	-
1	FRONT BUMPER GRILLE LH	NOT NECESSARY	186.50	-
1	FRONT DAY LIGHT LH	NOT NECESSARY	642.50	-
1	FRONT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	HEAD LAMP LH	CRACKED	2,110.30	2,110.30
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	FRONT FENDER EMBLEM	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-924.96	-523.60
			3,699.84	2,094.40
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER CENTRE UPPER MOULDING AND FRONT FENDER LH.		750.00	375.00
	SPRAY PAINT.		600.00	500.00
	RESET FRONT WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	CHECK LIGHTING.		60.00	30.00
			1,470.00	905.00
	GRAND TOTAL		5,169.84	2,999.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,400.00

Report Ref No. NS/INC23003479/Tnp3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.