Adjuster Report 6/19/23, 2:15 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.

Our File No:

CS6/AIS23003486/HWP3E2

79 Robinson Road #09-01 Singapore 068897

Date:

19/06/2023

REFERENCE

Insured/Claimant: Date of Loss:

JOKIA PRIVATE LIMITED

Policy No: Nature of Claim: SPCM1000000252

Claim No:

202332006429

DESCRIPTION & IDENTIFICATION OF VEHICLE

19/03/2023

Reg No:

YQ7144L

HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M) Make & Model:

Engine No:

OD

N04CWN18199

Reg. Date:

27/05/2022 (Man. Year: 2022)

Chassis No:

JHHUCV3F10K044239

Colour:

White

Odometer:

36331 km

Engine Capacity:

4009 cc

Market Value/New Car Price: S\$115,000.00

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable):

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/85 R16

Rear Tyre Size:

195/85 R16

Front Left Side:

Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side:

Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,295.50	3,536.50	759.00	17.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,300.00	500.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,095.50	4,836.50	1,259.00	20.65
Approved Total (Overridden) (S\$)		3,350.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	6,095.50	2,750.00	3,345.50	54.88
+ GST 8.00/8.00% (S\$)	487.64	220.00	267.64	54.88
Nett Amount (S\$)	6,583.14	2,970.00	3,613.14	54.88

INSPECTION

Date of Assignment:

01/04/2023

Present Location:

Cheng Auto Bodyworks (HQ) Cheng Auto Bodyworks (HQ)

Date Inspected:

03/04/2023

Inspected At:

5 Soon Lee Street #01-60, Pioneer Point

Singapore 627607

Estimated Period of Repair:

3.0 days

Manager:

SHIAU CHAN

Adjuster: Edward

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jun 2023)

Parts: N/A HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YQ7144L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

OOOR RH CP) OOOR RH HINGE UPPER CP) OOOR RH HINGE LOWER CP) OOOR LOCK ASSY CP) OOOR LH SIGNAL LAMP	Dented Not Necessary Not Necessary Not Necessary Broken	1,550.00 F 60.00 F 60.00 F 350.00 F	*1,550.00 F *- F *- F *- F
CP) OOR RH HINGE LOWER CP) OOR LOCK ASSY CP) OOR LH SIGNAL LAMP	Not Necessary Not Necessary	60.00 F	*-F
CP) OOR LOCK ASSY CP) OOR LH SIGNAL LAMP	Not Necessary		
CP) OOR LH SIGNAL LAMP		350.00 F	*- F
	Broken		
	Broken	60.00 F	*60.00 F
EADLAMP RH	Scratched	550.00 F	*550.00 F
RH SIDE MIRROR STAND ASSY	/ Dented	220.00 F	*220.00 F
H SIDE PARKING MIRROR	Cracked	120.00 F	*120.00 F
TEP GARNISH RH	Not Necessary	220.00 F	*- F
RT BUMPER (CP)	Cracked	450.00 F	*450.00 F
RT BUMPER BRACKET RH	Distorted	190.00 F	*190.00 F
OGLAMP RH	Missing	75.00 F	*75.00 F
		•	3,215.00
+ Margin on L,N Items 10.00/10.00% (S\$		390.50	321.50
	Total Parts (S\$)	4,295.50	3,536.50
	H SIDE MIRROR STAND ASSYCP) H SIDE PARKING MIRROR CP) TEP GARNISH RH CP) RT BUMPER CP) RT BUMPER BRACKET RH CP) OGLAMP RH	H SIDE MIRROR STAND ASSY CP) H SIDE PARKING MIRROR CP) TEP GARNISH RH CP) RT BUMPER CP) CRT BUMPER BRACKET RH CP) CP) OGLAMP RH CP) Sub Total (S\$) + Margin on L,N Items 10.00/10.00% (S\$)	H SIDE MIRROR STAND ASSY Dented 220.00 F CP

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	800.00	600.00
2	SPRAYPAINTING	New	800.00	600.00
3	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR/FACILITATE REPAIR	New	200.00	100.00
	Gross Labour Cost (S\$)			1,300.00
	Report was unsubmitted during this prin	nt-out.		

< END OF ESTIMATES >