



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 896L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR FENDER (RH) (CONSISTENT)	TO REPAIR SEE LABOUR	4,814.40	-
1	REAR FENDER UNDER GARNISH (RH) (CONSISTENT)	TORN	620.68	322.00
1	SET REAR FENDER INNER GARNISH CLIP (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR BUMPER (CONSISTENT)	DEEP CUT	1,575.30	1,440.00
1	REAR BUMPER SIDE RETAINER (RH) (CONSISTENT)	CRACKED	277.30	115.00
1	REAR SHOCK ABSORBER (RH)(CONSISTENT)	SERVICEABLE	407.10	-
1	REAR HUB BEARING (RH) (CONSISTENT)	DAMAGED	486.70	486.70
1	TAILLAMP (RH) (CONSISTENT)	NOT NECESSARY	236.00	-
	LESS 10% DISCOUNT		-847.75	-236.37
			7,629.73	2,127.33
<u>SPECIAL NETT ITEMS</u>				
1	REAR TYRE RIM (RH) (SN) (CONSISTENT)	WARPED	650.00	500.00
			650.00	500.00
<u>LABOUR</u>				
	TO REMOVE & REINSTALL REVERSE SENSORS.		80.00	40.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		120.00	20.00
	TO REMOVE & INSTALL RHR UNDERCARRIAGES.		280.00	150.00
	TO REMOVE & INSTALL RHR TYRE RIM.	NOT NECESSARY	50.00	-
	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER (RH).		1,500.00	420.00
	TO PUTTY AND RESPRAY AFFECTED AREAS.		980.00	500.00
			3,010.00	1,130.00
GRAND TOTAL			11,289.73	3,757.33
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/HSB23003488/Uqp3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.