

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23003491/KVP3Q2**Date:** 06/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00090702200

Claimant Vehicle No : GBD9530H **Insured Vehicle No :** GBL9170X

Date of Loss: 06/03/2023 Nature of Claim: TP Claim No: SNM23D201748/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD9530H**

Make & Model: TOYOTA DYNA 150, 3.0 D (M) Engine No: 1KD2490882

Reg. Date: 03/08/2015 (Man. Year: 2015) Chassis No: KDY2318018979

Colour: Silver Odometer: 340585 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D)

Front Left Side: Michelin 9 mm Rear Left Side: Grenlander 9/9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Grenlander 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,458.30	2,494.40	1,963.90	44.05
Miscellaneous Items	760.00	690.00	70.00	9.21
Labour	2,800.00	2,550.00	250.00	8.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,018.30	5,734.40	2,283.90	28.48
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	8,018.30	5,700.00	2,318.30	28.91
+ GST 8.00/0.00% (S\$)	641.46	0.00	641.46	100.00
Nett Amount (S\$)	8,659.76	5,700.00	2,959.76	34.18

INSPECTION

Date of Assignment: 03/04/2023 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 28/03/2023 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jun 2023)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD9530H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC TAILGATE	Bent	550.00 F	*550.00 FL
2	1		*1 PC TAILGATE STICKER (DYNA)	Necessary	20.00 F	*20.00 FL
3	1		*1 PC TAILGATE STICKER (1500 KG)	Necessary	30.00 F	*30.00 FL
4	1		*1 PC TAILGATE RH LOCK HANDLE	Distorted	55.00 F	*55.00 FL
5	1		*1 PC TAILGATE RH SAFETY LOCK	Bent	40.00 F	*40.00 FL
6	1		*1 PC TAILGATE RH HINGE	Bent	52.00 F	*52.00 FL
7	1		*1 PC RH TAILLAMP	Broken	105.00 F	*105.00 FL
8	1		*1 PC RH TAILLAMP PANEL	Bent	48.00 F	*48.00 FL
9	1		*1 PC REAR REFLECTOR	Cracked	28.00 F	*28.00 FL
10	1		*1 PC LH TAILLAMP	Cracked	105.00 F	*105.00 FL
11	1		*1 PC RH SIDE GATE	Bent	650.00 F	*650.00 FL
12	1		*1 PC FRT BUMPER	Buckled	220.00 F	*220.00 FL
13	1		*1 PC FRT BUMPER LH BRACKET	Repair	105.00 F	*- FL
14	1		*1 PC FRT BUMPER LH FOG LAMP	Repair	100.00 F	*- FL
15	1		*1 PC FRT BUMPER LH FOG LAMP GARNISH	Serviceable	60.00 F	*- FL
16	1		*1 PC FRT LH CORNAL PANEL	Bent	90.00 F	*90.00 FL
17	1		*1 PC FRT LH CORNAL GARNISH	Serviceable	50.00 F	*- FL
18	1		*1 PC LH HEADLAMP	Cracked	300.00 F	*300.00 FL
19	1		*1 PC AIR-CON CONDENSER	Bent	450.00 F	*450.00 FL
20	1		*1 PC FRT LH DOOR	Repair	620.00 F	*- FL
21	1		*1 PC FRT PANEL STICKER (DYNA)	Necessary	30.00 F	*30.00 FL
22	1		*1 PC RH HEADLAMP	Cut	300.00 F	*300.00 FL
23	1		*1 PC FRT RH DOOR LAMP	Cracked	45.00 F	*45.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	4,053.00 3,118.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 623.60
					+ Margin on L,N Items 10.00/0.00% (\$\$)	405.30 0.00
					Total Parts (\$\$)	4,458.30 2,494.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC RH RAILING (BENT)	350.00	350.00
2	1	1 PC STICKER - 13 PAX (NECESSARY)	10.00	10.00
3	1	1 PC STICKER - 70KM/H (NECESSARY)	10.00	10.00
4	1	1 PC TAILGATE INNER PROTECTOR (BENT)	350.00	280.00
5	1	2 PCS FRT DOOR COY STICKERS @20/PC (NECESSARY)	40.00	40.00
Sub Total (\$\$)			760.00	690.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX TAILGATE ASSY, RH SIDE GATE, TO KNOCK & REPAIR CABIN REAR RH PILLAR, FRT PANEL, FRT RH DOOR, REAR TRUCK END MEMBER, RH SIDE MEMBER AND REALIGN REAR TRUCK POSTION.	New	1,200.00	1,100.00
2	PUTTY & RESPRAY ON FRT PANEL, FRT BOTH DOORS, BOTH HEADLAMPS ETC, TAILGATE, RH SIDE GATE, LOWER MEMBER, CABIN REAR RH PILLAR	New	1,500.00	1,350.00
3	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
Gross Labour Cost (\$\$)			2,800.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >